

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NAB1520553647*

**OPERATOR**

Initial Report  Final Report

Name of Company: BOPCO, L.P. <i>2100737</i>	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: PLU CVX JV PC 003H (AKA PLU PC 28)	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner:
API No. 3001536830	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	28	24S	30E	350		850		Eddy

Latitude: 32.182164 Longitude: 103.879997

**NATURE OF RELEASE**

Type of Release: Oil and Produced water	Volume of Release: 9 barrels oil, 19 barrels PW	Volume Recovered: 5 barrels oil, 15 barrels PW
Source of Release: Gasket of FWKO failed	Date and Hour of Occurrence: 7-20-15 @ 12:30pm	Date and Hour of Discovery: 7-20-15 @ 12:56pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher, Heather Via email	
By Whom? Bradley Blevins	Date and Hour: 7-20-15 @ 4:31pm	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* Gasket on FWKO failed and released oil and water to the lined containment and also sprayed the location surrounding the production equipment.		
Describe Area Affected and Cleanup Action Taken.* A vacuum truck and steam cleaner was called to location, the vacuum truck recovered 15 barrels of produced water and 5 barrels of oil from inside the lined containment. No fluid was recovered from the spray area on location.		

**NM OIL CONSERVATION**  
ARTESIA DISTRICT  
JUL 24 2015

RECEIVED

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Bradley Blevins</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Bradley Blevins	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date: 7/24/15	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7-24-15 Phone: 432-214-3704	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 8/27/15

2RP-3153

Attach Additional Sheets If Necessary