

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 24 2015

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

RECEIVED
Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

NAB1520834022

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Superfortress 29 Federal #3H	Facility Type: Battery
Surface Owner: Federal	Mineral Owner: Federal
API No. 30-015-38642	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	29	19S	31E	330	North	2200	West	Eddy

Latitude 32.6377373 Longitude -103.8928909

NATURE OF RELEASE

Type of Release: Oil	Volume of Release: 36 bbls oil	Volume Recovered: 34 bbls oil
Source of Release: Valve	Date and Hour of Occurrence: 7/6/2015 10:30 am	Date and Hour of Discovery: 7/6/2015 10:30 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Jim Amos - BLM	
By Whom? <i>Amanda Trujillo</i>	Date and Hour: Fri 7/10/2015 2:45 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
The release was caused when a valve was left open after a transducer was calibrated. Vacuum trucks were dispatched to recover all the standing fluid.

Describe Area Affected and Cleanup Action Taken.*
This release occurred within a lined facility and all fluid was able to be recovered. The facility was cleaned, repaired and put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: <i>7/27/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>atrujillo@concho.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: July 20, 2015 Phone: 575-748-6940		

* Attach Additional Sheets If Necessary

2RP-3155