

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

**OPERATOR** ☒ Initial Report ☐ Final Report

**Name of Company:** BOPCO, L.P. **Contact:** Tony Savoie  
**Address:** 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 **Telephone No.** 575-887-7329  
**Facility Name:** James Ranch Unit #074 **Facility Type:** Exploration and Production

**Surface Owner:** Federal **Mineral Owner:** Federal **API No.** 30-015-31168

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
D	6	23S	31E	330	North	430	West	Eddy

Latitude N 32.339824° Longitude W 103.824221°

NATURE OF RELEASE

Type of Release: Crude oil & Produced Water	Volume of Release: 3 bbls. oil & 11 bbls. PW	Volume Recovered: 2 bbls. oil & 1 bbl. PW
Source of Release: 1/4" Pressure gauge	Date and Hour of Occurrence: 7/25/15 time unknown	Date and Hour of Discovery: 7/25/15 at approximately 10:00 a.m.
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 28 2015

RECEIVED

Describe Cause of Problem and Remedial Action Taken.\*

A 1/4" gauge on the wellhead failed internally releasing oil and water on to the wellhead pad. A valve to the gauge was shut until the gauge could be replaced.

Describe Area Affected and Cleanup Action Taken.\* The spill impacted approximately 365 sq.ft. of the bermed wellhead and pad area. All of the free standing fluid was recovered with a vacuum truck.  
The stained are will be cleaned up in accordance to the NMOCD and BLM remediation guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Tony Savoie</i>	OIL CONSERVATION DIVISION	
Printed Name: Tony Savoie	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Waste Management and Remediation Specialist	Approval Date: 7/28/15	Expiration Date: N/A
E-mail Address: tasavoie@basspet.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 7/28/15 Phone: 432-556-8730	Remediation per O.C.D. Rules & Guidelines	

SUBMIT REMEDIATION PROPOSAL NO

LATER THAN: 7/30/15

2RP-3165

\* Attach Additional Sheets If Necessary