

**NM OIL CONSERVATION**

ARTESIA DISTRICT

JUL 28 2015

Form C-141

Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Sub **RECEIVED** appropriate District Office in accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

*NAB1521048843*

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: PINE SPRINGS 2 STATE SWD #001	Facility Type: SWD

Surface Owner: State	Mineral Owner:	API No. 30-015-42348
----------------------	----------------	----------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
K	2	26S	25E	2500	SOUTH	2500	WEST	EDDY

Latitude 32.071434 Longitude -104.3667831

**NATURE OF RELEASE**

Type of Release: PRODUCED WATER	Volume of Release: 400	Volume Recovered: 395
Source of Release: LIGHTNING CAUSED FIRE	Date and Hour of Occurrence: 7/11/2015 8:00 pm	Date and Hour of Discovery: 7/11/2015 8:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: Sat 7/11/2015 11:18 AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*  
The release was caused by a lightning strike and resulted in a fire. Local fire crews responded to the incident. Vacuum trucks were dispatched to recover all standing fluid.

Describe Area Affected and Cleanup Action Taken.\*  
This release occurred within a lined facility. The facility was cleaned and the damaged equipment replaced before being put back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Amanda Trujillo	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: <i>7/29/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>atrujillo@concho.com</i>	Conditions of Approval: <i>FINAL</i>	Attached <input type="checkbox"/>
Date: July 25, 2015 Phone: 575-748-6940		

\* Attach Additional Sheets If Necessary

*2RP-3172*