## NM OIL CONSERVATION

ARTESIA DISTRICT		
Onice Enormy M	tate of New Mexico	Form C-103 Revised November 3, 2011
District I  1625 N. French Dr., Hobbs, NM 88240  District II  District II  District II  District II  District II  DECEIVED		WELL API NO. 30-015-03282
District II 811 S. First St., Artesia, NM 88210 REGIVEON	st St., Artesia, NM 88210  RECEIVED  RECEIVED  1220 S. 11 St. F. D.	
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		STATE FEE 6. State Oil & Gas Lease No.
District IV  1220 S. St. Francis Dr., Santa Fe, NM  87505		6. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WLH G4S Unit Tract 43
1. Type of Well: Oil Well Gas Well Other		8. Well Number 001
2. Name of Operator EnerVest Operating, LLC		9. OGRID Number 143199
3. Address of Operator	a solico	10. Pool name or Wildcat
1001 Fannin, Ste. 800 Houston, Texas 77002	"Denied"	Loco Hills Queen-Grayburg-San
4. Well Location		
Unit Letter P: 330 feet from the South line and 330 feet from the East line		
Section 4 Township 18S Range 29E 'NMPM Eddy County  11. Elevation (Show whether DR, RKB, RT, GR, etc.)		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO		SEQUENT REPORT OF:
		<del>_</del>
PULL OR ALTER CASING MULTIPLE CO		<del></del>
OTHER:		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been remove from lease and well location.		
All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed.)		
<ul> <li>✓ All other environmental concerns have been addressed as per OCD rules.</li> <li>✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-</li> </ul>		
retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease: all electrical service poles and lines have been removed from lease and well least for utility's distribution infrastructure.		
location, except for utility's distribution infrastructure.  When all work has been completed, return this form to the appropriate District office to schedule an inspection.		
SIGNATURE Sheep Does et en TITLE Agent DATE: 07/19/2015		
THE Agent DATE. WHOMEN		
TYPE OR PRINT NAME: Shelly Doescher E-MAIL: sdoescher@enervest.net PHONE:505-320-5682		
For State Use Only APPROVED		
BY: DATE SIALS conditions of		
APPROVED  BY: Down To a las TITLE Compliance Of our DATE \$1218 conditions of Approval (if any):  Approval (if any):  Re lease No 5teel Mar Wer		
AD 11 DI HE 1600	se 110 5/66/1	1. To wer