

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1522939771

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Cougar Fed Com #1 Battery	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-29950

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	35	18S	29E					Eddy County, NM

Latitude N 32.70858° Longitude W 104.04045°

NATURE OF RELEASE

Type of Release	Oil and produced water	Volume of Release	50 bbls oil, 25 bbls produced water	Volume Recovered	0 bbls
Source of Release	Internal corrosion of the central oil tank	Date and Hour of Occurrence	07/28/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson-NMOCD, Shelly Tucker-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	07/28/2015 @ 3:07 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

NM OIL CONSERVATION
ARTESIA DISTRICT
AUG 14 2015
RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

Internal corrosion of the central oil tank caused 50 bbls of oil and 25 bbls of produced water onto the ground. The fluids were not recoverable and the tank was repaired or removed.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 75' x 35' on location inside the firewall. Remediation will be completed according to a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name:	CJ Summers	Approved by Environmental Specialist:	
Title:	HES Lead	Approval Date:	8/17/15
E-mail Address:	chancey_summers@oxy.com	Expiration Date:	N/A
Date:	8-13-15	Conditions of Approval:	
Phone:	(432) 685-5824	Attached	<input type="checkbox"/>

* Attach Additional Sheets If Necessary

Remediation per O.C.D. Rules & Guidelines
SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 9/18/15

2RP-3202