

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1522950454

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Oxy Permian Ltd.	Contact	CJ Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(432) 685-5824
Facility Name	Hackberry 6 Fed Com #4H	Facility Type	Well
Surface Owner	BLM	Mineral Owner	
		API No.	30-015-41248

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	6	19S	31E					Eddy County, NM

Latitude N 32.69558° Longitude W 103.91203°

NATURE OF RELEASE

Type of Release	Oil	Volume of Release	8 bbls	Volume Recovered	6 bbls
Source of Release	Over pressure on the stuffing box caused the packing to blow out of the well head	Date and Hour of Occurrence	07/19/2015	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher and Heather Patterson-NMOCD, Shelly Tucker and James Amos-BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	07/20/2015 @ 4:06 pm	NM OIL CONSERVATION	
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	ARTESIA DISTRICT		

If a Watercourse was Impacted, Describe Fully.*

AUG 14 2015

RECEIVED

Describe Cause of Problem and Remedial Action Taken.*

Over pressure on the stuffing box caused the packing to blow out on the well head and spill 8 bbls of oil onto the ground. A vacuum truck recovered 6 bbls of oil and the packing was replaced.

Describe Area Affected and Cleanup Action Taken.*

The affected area is approximately 105' x 40' on location. Remediation will be completed according to a remediation plan approved by NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	OIL CONSERVATION DIVISION		
Printed Name: CJ Summers	Approved by Environmental Specialist:		
Title: HES Lead	Approval Date: 8/17/15	Expiration Date: N/A	
E-mail Address: chancey_summers@oxy.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 8-13-15	Phone: (432) 685-5824	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 9/18/15

22P-3204