

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR Initial Report Final Report

Name of Company: BOPCO, L.P. *210737* **Contact:** Amy Ruth
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220 **Telephone No.** 575-887-7329
Facility Name: Indian Flats Bass Federal SWD (SWD is located 2996 ft. SW of Well #1 Apl 30-015-24968) **Facility Type:** Exploration and Production

Surface Owner: Federal **Mineral Owner:** Federal **API No.** 30-015-24968

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	35	21S	28E	1652	South	2150	East	Eddy

Latitude 32.433935° Longitude -104.055036°

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 8 bbls	Volume Recovered 1 bbls
Source of Release 1/2" fitting on SWD pump	Date and Hour of Occurrence 8/13/2015 unknown time	Date and Hour of Discovery 8/13/2015 10:30 pm
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? N/A	
By Whom? N/A	Date and Hour N/A	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* A 1/2" inch fitting on the discharge side of the east SWD pump failed. Pump shut down and fitting was repaired.		
Describe Area Affected and Cleanup Action Taken.* The leak affected approximately 3,058 square ft. area of caliche pad directly south of the SWD containment and surrounding containment on all sides. A vac truck recovered fluids from the zero perm containment as well as from the ground. The leak on the caliche is within an area previously lined with 20-mil plastic. The saturated surface soils were scraped up and removed to a NMOCD approved disposal facility.		

NM OIL CONSERVATION
ARTESIA DISTRICT
AUG 17 2015

RECEIVED

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>[Signature]</i>	OIL CONSERVATION DIVISION	
Printed Name: Amy Ruth	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Assistant Remediation Foreman	Approval Date: 8/19/15	Expiration Date: N/A
E-mail Address: ACRuth@basspet.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 8/17/2015 Phone: 432-661-0571	SUBMIT REMEDIATION PROPOSAL NO	

LATER THAN: 9/21/15

2RP-3212

* Attach Additional Sheets If Necessary