

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

AUG 25 2015

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB 1523931622

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	Contact	Daniel Suniga
Address	6488 Seven Rivers Hwy Artesia, NM 88220	Telephone No.	575-390-5850
Facility Name	Ore Ida 14 Fed 10	Facility Type	Oil

Surface Owner	Federal	Mineral Owner	Federal	API No.	30-015-29290
---------------	---------	---------------	---------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	14	24S	29E	1980	South	660	East	Eddy

Latitude: N 32°21'53.45"

Longitude: W 103°94'90.29"

NATURE OF RELEASE

Type of Release Spill Produced Water and Oil	Volume of Release 85 bbls	Volume Recovered 60 bbls
Source of Release Pump malfunction	Date and Hour of Occurrence 8/21/2015 @ 10:41 PM	Date and Hour of Discovery 8/21/2015 @ 10:41 PM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM OCD	
By Whom? David Simmons	Date and Hour August 21, 2015 @ 11:26 PM August 21, 2015 @ 11:31 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

Lease operator arrived at location and discovered that the water tank was over flowing causing an 85 bbl produced water and oil spill into lined containment. The pump was reset and within a minute the tank stopped from over flowing. Black River Trucking was called out and they were able to recover 60 bbls of produced water and oil.

Describe Area Affected and Cleanup Action Taken.*

Black River Trucking was called out and they were able to recover 60 bbls of produced water and oil. Environmental agency will be contacted for cleanup.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Corina Moya	OIL CONSERVATION DIVISION	
Printed Name: Corina Moya	Signed By <u>M. L. Brannon</u>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: corina.moya@dvn.com	Approval Date: 8/27/15	Expiration Date: N/A
Date: 8/25/2015 Phone: 575.746.5559	Conditions of Approval:	Attached <input type="checkbox"/>
mediation per O.C.D. Rules & Guidelines		

MIT REMEDIATION PROPOSAL NO

LATER THAN: 9/27/15

2RP-3222

* Attach Additional Sheets If Necessary