

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1524338300

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company: COG Operating LLC	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Big Papi Federal Com #2H	Facility Type: Well

Surface Owner: Federal	Mineral Owner:	API No. 30-015-37833
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter C	Section 4	Township 26S	Range 29E	Feet from the 330'	North/South Line North	Feet from the 1980'	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	------------------------	------------------------	----------------

Latitude 32.0780182 Longitude -103.9915085

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 125 bbls PW	Volume Recovered: 120 bbls PW
Source of Release: Flowline	Date and Hour of Occurrence: 8/7/2015 7:00 am	Date and Hour of Discovery: 8/7/2015 7:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD / Jim Amos - BLM	
By Whom? Lupe Carrasco	Date and Hour: Saturday, August 08, 2015 2:18 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

NM OIL CONSERVATION  
ARTESIA DISTRICT

AUG 28 2015

RECEIVED



Describe Cause of Problem and Remedial Action Taken.\*

This release was caused a poly flowline. Vacuum trucks were dispatched to recover all standing fluids and repairs were made to the line.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred along the road in an area about 20' x 100'. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Approved by Environmental Specialist: 	
Title: Senior Environmental Coordinator	Approval Date: 8/31/15	Expiration Date: N/A
E-mail Address: atrujillo@concho.com	Conditions of Approval:	
Date: 8/21/2015 Phone: 575-748-6940	Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 10/21/15	

Attached ☐

\* Attach Additional Sheets If Necessary

2RP-322B