

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

SEP 01 2015

Form C-141
Revised August 8, 2011

RECEIVED
This report should be submitted to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1524533692

OPERATOR

Initial Report Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: Flying Squirrel Federal #1H	Facility Type: Battery

Surface Owner: Federal	Mineral Owner:	API No. 30-015-42608
------------------------	----------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	30	18S	31E	2000'	South	450'	East	Eddy

Latitude 32.7167244 Longitude -103.9017334

NATURE OF RELEASE

Type of Release: Oil & Produced Water	Volume of Release: 20 bbls Oil ; 8 bbls PW	Volume Recovered: 3 bbls Oil ; 3 bbls PW
Source of Release: Gasket Failure	Date and Hour of Occurrence: 8/11/2015 6:30 pm	Date and Hour of Discovery: 8/11/2015 6:30 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Kellie Jones - NMOCD	
By Whom? Amanda Trujillo	Date and Hour: Thu 8/13/2015 5:56 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*
This release was caused by a gasket failure on FWKO. A vacuum truck was dispatched to recover all standing fluid. Crews with soapy water and Microblaze were also dispatched to treat the area.

Describe Area Affected and Cleanup Action Taken.*
This release caused a spray that impacted the nearby pasture. Concho will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>A Trujillo</i>	OIL CONSERVATION DIVISION	
Printed Name: Amanda Trujillo	Signed By <i>Mike Brandon</i> Approved by Environmental Specialist:	
Title: Senior Environmental Coordinator	Approval Date: <i>9/1/15</i>	Expiration Date: <i>N/A</i>
E-mail Address: atrujillo@concho.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 8/25/2015 Phone: 575-748-6940	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 10/1/15

2RD-3234