

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1524452333 OPERATOR Initial Report Final Report

Name of Company RKI E&P, LLC <i>246289</i>	Contact Taylor Jones
Address 210 Park Ave. - Ste. 700, OKC, OK 73102	Telephone No. 405-996-5782
Facility Name: MWJ Federal 1	Facility Type : Tank Battery
Surface Owner Federal	Mineral Owner NA
API No. 30-015-24262	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	35	26S	29E		660 FNL		660FEL	Lea

Latitude: 32.0033035 Longitude: -103.9490051

NATURE OF RELEASE

Type of Release: Produced Water & Crude Oil	Volume of Release: 15 Bbbls	Volume Recovered: 0 Bbbls
Source of Release Heater Treater Failure	Date and Hour of Occurrence 8/31/15 - 1000 MT	Date and Hour of Discovery 08/31/15 - 1000hrs MT
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Heater Treater failed and ruptured, causing both produced water and crude oil contained inside to be released, primarily as a spray/mist. Heater treater will be replaced and damaged piping repaired.		
Describe Area Affected and Cleanup Action Taken.* The spray/misting nature of this incident allowed fluid to leave containment and affect well pad as well as offsite in immediate vicinity. Affected soil is being scraped by backhoe and will be hauled off to disposal		

NM OIL CONSERVATION
ARTESIA DISTRICT
SEP 02 2015
RECEIVED

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Taylor Jones</i>	OIL CONSERVATION DIVISION	
Printed Name: Taylor Jones	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: EHS Systems Specialist	Approval Date: 9/3/15	Expiration Date: NA
E-mail Address: TJones@rkixp.com	Conditions of Approval:	
Date: 09/02/15 Phone: 405-996-5782	Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	

REMIT REMEDIATION PROPOSAL NO
LATER THAN: 10/4/15 **2RP-3235**

* Attach Additional Sheets If Necessary