

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

30-005-00069

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company Morris A Richardson dba Fairview Production Co.	Contact John Elliott
Address PO Box 1995 Muldrow, OK 74948	Telephone No. 918-261-6700
Facility Name Dekalb Federal #3	Facility Type Oil Well

Surface Owner	Mineral Owner	Lease No. NM-05876
---------------	---------------	--------------------

LOCATION OF RELEASE

Unit Letter E	Section 27	Township 10S	Range 25E	Feet from the 1980'	North/South Line North	Feet from the 660'	East/West Line West	County Chaves
---------------	------------	--------------	-----------	---------------------	------------------------	--------------------	---------------------	---------------

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release Produced Oil & Water	Volume of Release 1/2 Bbl	Volume Recovered 1/2 Bbl
Source of Release Stuffing box leak at wellhead	Date and Hour of Occurrence 11/21/05 Evening	Date and Hour of Discovery 11/22/05 Morning
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher (OCD) Stan Mayo (BLM)	
By Whom? Stan Thompson	Date and Hour 11/22/05 Morning	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

NOV 28 2005



Describe Cause of Problem and Remedial Action Taken.*

Stuffing box leaking around wellhead. Re-packed stuffing box and leak eliminated.

Describe Area Affected and Cleanup Action Taken.*

Contaminated soil has been scraped up and mixed with clean soil and spread onto plastic sheeting to dry. Once dry, all contaminated soil will be removed from premises to authorized disposal site. Clean soil will be brought in if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: John S Elliott	TIM GUM by MB 	
Title: Member	Approval Date: 12/5/05	Expiration Date:
E-mail Address: pohi82@yahoo.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 11/23/05	Phone: 918-261-6700	

* Attach Additional Sheets If Necessary

Imaged