

1/6/2006

Wellbore Diagram

r263

30-015-34325-00-00

SKELLY UNIT No. 962

Company Name: CHEVRON U S A INC

Location: Sec: 23 T: 17S R: 31E Spot:

Lat: Long:

Property Name: SKELLY UNIT

County Name: Eddy

String Information

Cement Information

Perforation Information

Top (ft sub)	Bottom (ft sub)	Shts/Ft	No Shts	Dt Sqz
0	0			

Formation Information

St Code	Formation	Depth
Prust	Rustler	473
Psal	Salado	672
Pbslt	Base of Salt	1667
Psr	Seven Rivers	2173
Psrbs	Bowers Sand	2575
Pqu	Queen	2790
Psa	San Andres	3540
Plvsd	Lovington Sand	3653
Pgl	Glorieta	5030

Hole: Unknown

TD:

TVD: 0

PBTD: