

Submit 3 Copies To Appropriate District Office  
District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Ave., Artesia, NM 88210  
District III  
1000 Rio Brazos Rd., Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy, Minerals and Natural Resources

Form C-103  
Revised June 10, 2003

OIL CONSERVATION DIVISION  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

WELL API NO. 30 015 01801
5. Indicate Type of Lease STATE <input checked="" type="checkbox"/> FEE <input type="checkbox"/>
6. State Oil & Gas Lease No.
7. Lease Name or Unit Agreement Name Artesia Unit
8. Well Number Well # 54
9. OGRID Number 184860
10. Pool name or Wildcat Artesia (Queen, Grayburg, SA)

SUNDRY NOTICES AND REPORTS ON WELLS  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well:  
Oil Well ☒ Gas Well ☐ Other (Injection) ☐

RECEIVED

2. Name of Operator  
Melrose Operating Company

DEC 22 2005

3. Address of Operator  
c/o P.O. Box 953, Midland, TX 79702

OCD-ARTESIA

4. Well Location

Unit Letter C 1070 feet from the North line and 1570 feet from the West line

RECEIVED

JAN 23 2006

Section 3 Township 18S Range 28E NMPM Eddy County

OCD-ARTESIA

11. Elevation (Show whether DR, RKB, RT, GR, etc.)

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☐

TEMPORARILY ABANDON ☐ CHANGE PLANS ☐

PULL OR ALTER CASING ☐ MULTIPLE COMPLETION ☐

OTHER: ☐

SUBSEQUENT REPORT OF:

REMEDIAL WORK ☒ ALTERING CASING ☐

COMMENCE DRILLING OPNS. ☐ PLUG AND ABANDONMENT ☐

CASING TEST AND CEMENT JOB

OTHER: (Order No. R-11720-A)

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

11-16-05: Rig up wireline, log cement top @ 1730'. Shot 2 squeeze holes @ 1700'. RIH w/packer, RBP & tubing, set RBP @ 1800' & test to 500#. Pull packer above squeeze holes, pumped 100 bbls @ 2 bbls/min @ 1000#. TIH & dumped 2 sx sand on RBP. SI.

11-17/21-05: Set cement retainer @ 1632'. Pumped 200 sx CI C w/2% CaCl. SI.

11-22-05: Rig up wireline, log top of cement @ 234'. Shot squeeze @ 195'.

11-23-05: Pumped 275 sx CI C 3% CaCl, circulate 20 sx good cement to surface.

11-28/30-05: Drilled out cement & through retainer @ 1632'.

12-1-05: Rigged up BJ Services, went in hole to 90' & set packer. Pumped 200 sx CI C cement w/3% CaCl.

12-2-05: RIH & tagged cement @ 120'.

12-9-05: Rigged up Rising Star, pumped 250 sx CI C w/2% CaCl. SI.

12-13/14-05: Drilled out cement to 1716', pulled RBP out. RIH w/AD-I packer & 2 3/8" plastic coated tubing to 2300'. Prep for test.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Ann E. Ritchie TITLE Regulatory Agent DATE 12-20-05

Type or print name Ann E. Ritchie E-mail address ann.ritchie@nmtor.net Telephone No. 432 684-6381

(This space for State use)

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_

Accepted for record  
NMOCD

Case 13199  
R-11720-A

1/18/06

Van/BRYAN; "MELROSE"

ARTESIA UNIT

I looked this over — a couple of wells still look marginal but they MAY be OK! Others look good.

I saved one copy of each SUNDRY and will scan them into R-11720-A (Case 13199). The original + one copy of each + the CBL's are being mailed BACK for your SIGNATURE/Scanning.

(This is work done BY Melrose in compliance with the above ORDER on wells:)

RECEIVED

JAN 23 2006

OOD-ARTESIA

30-015-01801	Well 54	OK
01798	Well 55	QUESTIONABLE —
01800	Well 37	QUESTIONABLE —
02541	Well 46	OK
01788	Well 53	OK
01799	Well 40	OK

Many other wells require work in this ORDER.

Will Jones