

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

Form C-141
Revised August 8, 2011

DEC 08 2015

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1534452923

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production	10137	Contact	Ruben Garcia Assistant Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88220		Telephone No.	575.748.5209
Facility Name	Todd 36 State I		Facility Type	SWD

Surface Owner	State	Mineral Owner	Federal & State	API No.	30-015-20341
---------------	-------	---------------	-----------------	---------	--------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	26	23S	31E	990	FSL	1980	FEL	Eddy

Latitude: 32.271810 Longitude: -103.744224

NATURE OF RELEASE

Type of Release Spill	Produced water	Volume of Release	1160 BBL	Volume Recovered	30 BBL
Source of Release	Water line leak	Date and Hour of Occurrence	12/03/15 at 3:45 pm	Date and Hour of Discovery	12/03/15 at 3:45 pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM Jim Amos OCD Mike Bratcher		
By Whom?	Ruben Garcia Production Assistant Foreman	Date and Hour	12/04/15 11:23 BLM 12/04/15 11:26 OCD		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

Corrosion caused a water line leak coming from the Todd 26 SWD going to the Todd 36 State I. Shut valve at the Todd 26 SWD and valve at the Todd 36 State I. Crew is currently working on repairing line.

Describe Area Affected and Cleanup Action Taken.*

1160 BBL of produced water was released and 30 BBL recovered by vacuum truck in a 21,681 square feet area. It was all on pasture, on the north side of lease road leading to the Todd 26 Fed 7. An environmental agency will be called out for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Jeanette Barron	OIL CONSERVATION DIVISION	
Printed Name: Jeanette Barron	Signed By <i>Mike Bratcher</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 12/10/15	Expiration Date: N/A
E-mail Address: Jeanette.barron@dmv.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines SUBMIT REMEDIATION PROPOSAL NO	
Date: 12/08/15 Phone: 575.748.1813	Attached <input type="checkbox"/> LATER THAN: 1/15/16	

* Attach Additional Sheets If Necessary

2RP-3438