

NM OIL CONSERVATION
ARTESIA DISTRICT

DEC 14 2015

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

RECEIVED
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1534957748 **OPERATOR** ☒ Initial Report ☐ Final Report

Name of Company	Burnett Oil Co., Inc. 3080	Contact	Leslie Garvis
Address	801 Cherry Street, Ste 1500, Ft. Worth, TX 76102	Telephone No.	817-583-8730
Facility Name	Partition Tank Battery	Facility Type	Tank Battery
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-38635

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
G	24	17S	31E	1395	North	2550	East	Eddy

Latitude _____ Longitude _____

NATURE OF RELEASE

Type of Release	Oil/produced water	Volume of Release	5 bbls/10 bbls	Volume Recovered	5 bbls/10 bbls
Source of Release	Gasket on water leg failed	Date and Hour of Occurrence	12/12/15 0700	Date and Hour of Discovery	12/12/15 0700
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	VMail - H. Patterson, OCD & S. Tucker, BLM		
By Whom?	Leslie Garvis	Date and Hour	12/12/15 09:15		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Gasket failed on water leg of heater treater and oil and produced water released into lined berm. Repair was made to line. Vac truck picked up standing fluid.

Describe Area Affected and Cleanup Action Taken.*
Produced water and oil was recovered. Tank battery is lined and has some caliche on the surface. Area will be scraped.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Leslie Garvis</i>	OIL CONSERVATION DIVISION	
Printed Name: Leslie Garvis	Approved by Environmental Specialist: <i>[Signature]</i>	
Title: Regulatory Coordinator	Approval Date: 12/15/15	Expiration Date: N/A
E-mail Address: lgarvis@burnettoil.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> Attached <input type="checkbox"/>	
Date: 12/14/15 Phone: 817-583-8730	SUBMIT REMEDIATION PROPOSAL NO	

* Attach Additional Sheets If Necessary

LATER THAN: 11/16/16 **2RP-3452**