

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

NAB 1601533272

**OPERATOR**

Initial Report  Final Report

Name of Company: COG Operating LLC <i>229137</i>	Contact: Robert McNeill
Address: 600 West Illinois Avenue, Midland TX 79701	Telephone No. 432-230-0077
Facility Name: G J WEST COOP UNIT #210	Facility Type: Battery
Surface Owner: State	Mineral Owner:
API No. 30-015-36703	

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	16	17S	29E	990'	North	1650'	West	Eddy

Latitude 32.8391876 Longitude - 104.0830383

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release: 90 bbls	Volume Recovered: 88 bbls
Source of Release: Pipe Fitting	Date and Hour of Occurrence: 11/22/2015 8:00 am	Date and Hour of Discovery: 11/22/2015 8:00 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - NMOCD	
By Whom? Lupe Carrasco	Date and Hour: Tuesday, November 24, 2015 2:32 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**NM OIL CONSERVATION**  
ARTESIA DISTRICT  
DEC 07 2015  
RECEIVED

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

This release was caused when a pipe fitting off a flange broke. Vacuum trucks were dispatched to recover the standing fluid.

Describe Area Affected and Cleanup Action Taken.\*

This release occurred within a lined facility. All standing fluids were able to be recovered; the facility was cleaned, repaired and returned to service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: <i>Amanda T. Davis</i>	Approved by Environmental Specialist: <i>[Signature]</i>	
Printed Name: Amanda Trujillo Davis	Approval Date: 11/15/16	Expiration Date: N/A
Title: Senior Environmental Coordinator	Conditions of Approval: FINAL	
E-mail Address: atrujillo@concho.com	Attached <input type="checkbox"/>	
Date: December 7, 2015 Phone: 575-748-6940		

\* Attach Additional Sheets If Necessary

2RD-399A