

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141  
Revised August 8, 2011

JAN 18 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*NAB1601927284*

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	Burnett Oil Co., Inc. <i>3080</i>	Contact	Leslie Garvis
Address	Burnett Plaza - Suite 1500, 801 Cherry Street-Unit 9, Ft. Worth, TX 76102	Telephone No.	817-583-8730
Facility Name	Jackson A 2	Facility Type	Tank Battery
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-37494

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	12	17S	30E	1115	South	2210	East	Eddy

Latitude \_\_\_\_\_ Longitude \_\_\_\_\_

**NATURE OF RELEASE**

Type of Release	Produced Water	Volume of Release	27 bbls	Volume Recovered	25 bbls
Source of Release	Poly Pipe	Date and Hour of Occurrence		Date and Hour of Discovery	1/17/2016 1000
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM - S. Tucker, OCD - H. Patterson		
By Whom?	Leslie Garvis	Date and Hour	01/12/2016 1500		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*  
N/A

Describe Cause of Problem and Remedial Action Taken.\*  
Leak in flowline. Contained within lined berm. Pipeline will be repaired and returned to service

Describe Area Affected and Cleanup Action Taken.\*  
Area affected is approx 20' x30' inside the lined berm. Vacuum truck was used to collect the standing water. Once the area is dry, we will assess the impacted area and see if any material needs to be removed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:	<i>Leslie Garvis</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Leslie Garvis	Approved by Environmental Specialist:	<i>[Signature]</i>
Title:	Regulatory Coordinator	Approval Date:	1/18/16
E-mail Address:	lgarvis@burnettoil.com	Expiration Date:	N/A
Date:	1/18/16	Conditions of Approval:	Remediation per O.C.D. Rules & Guidelines
Phone:	817-583-8730	Attached	<input type="checkbox"/>

**SUBMIT REMEDIATION PROPOSAL NO  
LATER THAN: 1/18/16**

\* Attach Additional Sheets If Necessary

2RP-3499