

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**NAB1604236407**

<b>OPERATOR</b>		<input checked="" type="checkbox"/> Initial Report	<input type="checkbox"/> Final Report
Name of Company	Judah Oil, LLC <b>245872</b>	Contact	James B Campanella
Address	P.O. Box 568, Artesia NM 88211-0568	Telephone No.	575-748-4730
Facility Name	Scottdale Federal	Facility Type	Oil gathering
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-25005

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
B	27	18S	31E					Eddy

Latitude 32.432877N Longitude 103.512230W

**NATURE OF RELEASE**

Type of Release	Oil and Produced Water	Volume of Release	3 oil/20 water	Volume Recovered	15 water
Source of Release	Open top water tank	Date and Hour of Occurrence	11-25-2015	Date and Hour of Discovery	11-26-2016
Was Immediate Notice Given?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
By Whom?	Date and Hour 12-14-2015 8:00 am				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*

**NM OIL CONSERVATION**  
ARTESIA DISTRICT

FEB 09 2016

Describe Cause of Problem and Remedial Action Taken.\*



Water Hauling Company hauled wrong tank battery. Called water truck and picked up standing fluid.

RECEIVED

Describe Area Affected and Cleanup Action Taken.\*

Unlined tank containment. Taking core samples to determine extent of contamination. Will submit remediation plan once core sample data is received and assessed. No ground water from surface to 300'

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: James B Campanella	Signed By:  Approved by Environmental Specialist:	
Title: Member/Manager	Approval Date: 2/11/16	Expiration Date: N/A
E-mail Address: judahoil@yahoo.com	Conditions of Approval:	
Date: February 8, 2016	Phone: 575-748-4730	

Remediation per O.C.D. Rules & Guidelines  
SUBMIT REMEDIATION PROPOSAL NO

Attached ☐

\* Attach Additional Sheets If Necessary

LATER THAN: 3/12/16

2RP-3543