NM OIL CONSERVATION ARTESIA DISTRICT

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 State of New Mexico **Energy Minerals and Natural Resources** 811 S. First St., Artesia, NM 88210

FEB 1 1 2016

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Submit 1 Copy to appropriate District Office in RECEIVED RECEIVED

Santa Fe, NM 87505

1220 S. St. Francis Dr., Santa Fe, NM 87505 **Release Notification and Corrective Action OPERATOR** Final Report Name of Company Devon Energy Production Company [0/37] Contact Matthew Nettles, Assistant Production Foreman **Telephone No.** 575-513-5767 Address 6488 Seven Rivers Hwy Artesia, NM 88210 Facility Name Cotton Draw Unit #135H Facility Type Oil Surface Owner Federal **Mineral Owner State** API No 30-015-38533 LOCATION OF RELEASE Unit Letter Section Township Range Feet from the North/South Line Feet from the East/West Line County Eddy Ν 2 **25S** 31E 200 South 1600 West

Latitude: N 32.15'27.67 Longitude: W 103.75'20.49

NATURE OF RELEASE		
Type of Release Spill Oil	Volume of Release 180 BBLS	Volume Recovered 175 BBLS
Source of Release	Date and Hour of Occurrence	Date and Hour of Discovery
Lact Unit pump housing	1/12/2016 @ 8:30pm	1/12/2016 @ 8:30pm
Was Immediate Notice Given?	If YES, To Whom?	
	OCD-Mike Bratcher	
	BLM-Jim Amos	
By Whom? Lolo Martinez, Lease Operator	Date and Hour	
	OCD- 1/12/2016 @ 10:35pm	
	BLM- 1/12/2016 @ 10:30pm	
Was a Watercourse Reached?	If YES, Volume Impacting the V	Vatercourse
☐ Yes ⊠ No	N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The Lact unit pump housing broke resulting in a release from the Lact unit. The tank load line valves were immediately shut down to prevent further release.		
Describe Area Affected and Cleanup Action Taken.* 180 BBLS of oil was released from the Lact unit onto location. The approximate area affected was 150ft x 75ft East of the Lact unit. All 180 BBLS oil released remained on location. None of the released fluid left location. Vacuum truck recovered approximately 175 BBLS of the released oil. Environmental Agency, Talon Lpe was contacted and has developed a work plan.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Sarah Gallegos-Troublefield	OIL CONSER	VATION DIVISION
7.0	Signed By	like Demosion
Printed Name: Sarah Gallegos-Troublefield	Approved by Environmental Special	ist:
	41	
Title: Field Admin Support	Approval Date: 2 2	Expiration Date: N/
E-mail Address: Sarah.Gallegos-Troublefield@dvn.com	அவில்வை(சிசிச்சில் C.D. Rui	les & Guideli Nus hed 🔲
Date:2/11/2016 Phone: 575.748.1864	PORMIT HEMEDIATION PR	OPOSAL NO
* Attach Additional Sheets If Necessary	LATER THAN: 3/6//	2RP-3551

District_II

District III

District IV

1000 Rio Brazos Road, Aztec, NM 87410