

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1613035815

246289

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	WPX Energy Inc/ RKI E&P, LLC	Contact	Lucas Smith
Address	3500 One Williams Center Tulsa, OK 74172	Telephone No.	539-573-0176
Facility Name:	Longview Federal 12-4H	Facility Type:	Oil and Gas Well

Surface Owner: Federal	Mineral Owner: Federal	API No. 30-015-42238
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	12	23S	28E	565	FNL	335	FEL	Eddy

Latitude: 32.0926101 Longitude: -103.9468205

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 30 Bbls	Volume Recovered: 28 Bbls
Source of Release Oil was pushed into the VRU line and out PRV	Date and Hour of Occurrence 05/04/16	Date and Hour of Discovery 05/04/16 - 1500hrs MT
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom? Spoke with Heather Patterson at 12:25 MT (Mobile)	
By Whom? Lucas Smith	Date and Hour: 04/16 1208hrs MT 5/4/16	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.* N/A


Describe Cause of Problem and Remedial Action Taken.*

Oil was pushed into the VRU line and out PRV. Currently the cause is under investigation

Describe Area Affected and Cleanup Action Taken.*

20bbls of crude oil was captured in a lined containment. 5bbls of crude oil were outside of containment and is being removed by vacuum truck. Remaining impacted soils will be removed for disposal.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Lucas Smith		Approved by Environmental Specialist: 	
Title: EHS Manager		Approval Date: 5/5/16	Expiration Date: N/A
E-mail Address: Lucas.smith@wpxenergy.com		Conditions: of APPROVAL	Attached <input type="checkbox"/>
Date: 05/04/16	Phone: 539-573-0176	Remediation per O.C.D. Rules & Guidelines	

* Attach Additional Sheets If Necessary

**SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: 6/1/16**

2RP-3676

**NM OIL CONSERVATION
ARTESIA DISTRICT
MAY 04 2016
RECEIVED**