

# NM OIL CONSERVATION

ARTESIA DISTRICT

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

MAY 16 2016

Form C-141  
Revised August 8, 2011

RECEIVED  
Submit Copy to appropriate District Office in accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

NAB1613450758

### OPERATOR

☒ Initial Report ☐ Final Report

Name of Company:	COG Operating LLC 229/37	Contact:	Robert McNeill
Address:	600 West Illinois Avenue, Midland TX 79701	Telephone No.	432-683-7443
Facility Name:	MYOX 6 STATE COM #012H	Facility Type:	Tank Battery

Surface Owner:	State	Mineral Owner:	API No.	30-015-37468
----------------	-------	----------------	---------	--------------

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	06	26S	28E	660	North	330	East	Eddy

Latitude 32.0771141

Longitude 104.1191025

### NATURE OF RELEASE

Type of Release: Oil and Produced Water	Volume of Release: 5bbls of Oil 10bbls of Produced Water	Volume Recovered: 0bbls of Oil 0bbls of Produced Water
Source of Release: Heater Treater	Date and Hour of Occurrence: 05-06-2016 09:30am	Date and Hour of Discovery: 05-06-2016 09:30am
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

Fire tube failure on the Heater Treater.

Describe Area Affected and Cleanup Action Taken.\*

The majority of the release was contained in the bermed area a 3' X 10' area in the pasture. The majority of the fluid was burnt up in the fire. Concho has replaced the fire tube on the heater treater and will have the spill site sampled to delineate any possible contamination from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation work.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Robert Grubbs Jr.</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: Robert Grubbs Jr.	Approved by Environmental Specialist: <i>M. L. Brachler</i>	
Title: Senior Environmental Coordinator	Approval Date: 5/17/16	Expiration Date: N/A
E-mail Address: rgrubbs@concho.com	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
Date: 05-16-2016 Phone: 432-683-7443	SUBMIT REMEDIATION PROPOSAL NO	

\* Attach Additional Sheets If Necessary

LATER THAN: 6/19/16

2RP-3696