

State of New Mexico  
Energy, Minerals and Natural Resources Department

Susana Martinez  
Governor

David Martin  
Cabinet Secretary

Tony Delfin  
Deputy Cabinet Secretary

David Catanach, Director  
Oil Conservation Division



**\*Response Required - Deadline Enclosed\***

*Field Inspection Program*  
*"Preserving the Integrity of Our Environment"*

07-Jul-16

TLT SWD, LLC  
P.O. BOX 1906  
HOBBS NM 88241

**LETTER OF VIOLATION - Inspection**

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

**INSPECTION DETAIL SECTION**

<b>STATE 2</b>	<b>No.004</b>	<b>K-2-23S-31E</b>	<b>30-015-35676-00-00</b>	
<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>
07/06/2016	Plug / Plug Back	Robert Byrd	Yes	No
<b>Comments on Inspection:</b>	Cannot release location, Pump jack and old tubing on location			
			<b>Corrective Action Due By:</b>	<b>Inspection No.</b>
			10/9/2016	iRB1618844463


<b>STATE 2</b>	<b>No.001</b>	<b>G-2-23S-31E</b>	<b>30-015-35678-00-00</b>	
<b>Inspection Date</b>	<b>Type Inspection</b>	<b>Inspector</b>	<b>Violation?</b>	<b>*Significant Non-Compliance?</b>
07/06/2016	Plug / Plug Back	Robert Byrd	Yes	No
<b>Comments on Inspection:</b>	Cannot release location, Tank battery, separator an old cattle guard and cellar boards on location			
			<b>Corrective Action Due By:</b>	<b>Inspection No.</b>
			10/9/2016	iRB1618844365

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Division Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

**Note:** Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data.  
\*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.

A handwritten signature in black ink, appearing to read "Robert J. Byrd". The signature is written in a cursive, flowing style.