

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

NM OIL CONSERVATION

ARTESIA DISTRICT

JUL 26 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141  
Revised August 8, 2011

Release Notification and Corrective Action

NAB 1121056944		OPERATOR		<input checked="" type="checkbox"/> Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company Devon Energy Production Company		Contact Jake Harrington, Production Foreman			
Address 6488 Seven Rivers Hwy Artesia, NM 88210		Telephone No. 432-214-5175			
Facility Name Cotton Draw Unit 89		Facility Type Salt Water Disposal			
Surface Owner Federal		Mineral Owner Federal		API No 30-015-31381	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	3	25S	31E	250'	FSL	1980'	FEL	Eddy

Latitude: 32.1528893

Longitude: -103.7636414

NATURE OF RELEASE

Type of Release Oil and Produced Water Release	Volume of Release 960bbls	Volume Recovered 960bbls
Source of Release Water tanks	Date and Hour of Occurrence July 24, 2016 @ 11:25 AM	Date and Hour of Discovery July 24, 2016 @ 11:25 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Mike Bratcher, OCD	
By Whom? Ray Carter, Asst. Production Foreman	Date and Hour Shelly Tucker, BLM July 24, 2016 @ 3:00 PM Mike Bratcher, OCD July 24, 2016 @ 3:05 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Transfer pumps went down while the Salt Water Disposal had lost communication causing the water tanks to run over with no alarms being sent out to the field. The pumps were reset and the inlet valve was closed to stop water from coming into the facility and continuing to overflow the tanks. Communication has been reestablished and the Salt Water Disposal is back in service.		
Describe Area Affected and Cleanup Action Taken.* Approximately 175bbls oil and 785bbls produced water was released into lined containment. A vacuum truck was called and recovered all 175bbls oil and 785bbls produced water from lined containment. Containment was checked for holes and none were found. No further action is required.		

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sheila Fisher	OIL CONSERVATION DIVISION	
Printed Name: Sheila Fisher	Signed By: Mike Bratcher	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: Sheila.fisher@dvn.com	Approval Date: 7/28/16	Expiration Date: N/A
Date: 7/26/16	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Phone: 575.748.1829		

\* Attach Additional Sheets If Necessary

ARP-3806