

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Received *ad/16* *TM*  
Form C-141  
Revised August 8, 2011  
Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

*NAB11022530649* *3080* OPERATOR ☒ Initial Report ☐ Final Report

Name of Company	Burnett Oil Co., Inc.	Contact	817-583-8730
Address	801 Cherry Street, Suite 1500, Fort Worth, TX 76102	Telephone No.	817-583-8730
Facility Name	Jackson B 5	Facility Type	Tank Battery
Surface Owner	BLM	Mineral Owner	BLM
		API No.	30-015-41191

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
P	I	17S	30E	1145'	South	1283'	East	Eddy

Latitude, Longitude

NATURE OF RELEASE

Type of Release	Oil/Water	Volume of Release	Sheen/5 BBLs	Volume Recovered	0 BBLs
Source of Release	Poly Line Rupture	Date and Hour of Occurrence	7/25/16 0730	Date and Hour of Discovery	7/25/16 0730
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?			
		BLM - S. Tucker, OCD - H. Patterson			
By Whom?	Date and Hour				
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			
If a Watercourse was Impacted, Describe Fully.*					
N/A					
Describe Cause of Problem and Remedial Action Taken.*					
Poly line ruptured at weld. Line will be repaired and return to service.					
Describe Area Affected and Cleanup Action Taken.*					
Impacted a 5'x 25' and 20'x15' area in pasture to the west of Jackson B 5 Tank Battery. Area will be remediated to regulatory standards.					
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.					
Signature: <i>Leslie Garvis</i>		OIL CONSERVATION DIVISION			
Printed Name: Leslie Garvis		Approved by Environmental Specialist: <i>[Signature]</i>			
Title: Regulatory Coordinator		Approval Date: <i>8/12/16</i>		Expiration Date: <i>N/A</i>	
E-mail Address: lgarvis@burnettoil.com		Conditions of Approval:			
Date: 7/25/16 Revised 8/9/16 Phone: 817-583-8730		Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>			
SUBMIT REMEDIATION PROPOSAL NO					

\* Attach Additional Sheets If Necessary

LATER THAN: *7/12/16*

*2RP-3805*