

State of New Mexico
 Energy, Mineral & Natural Resources Department

Susana Martinez
 Governor

David Martin
 Cabinet Secretary

Tony D
 Director

Tony D. Catanach, Director
 Conservation Division



OIL CONSERVATION
 DIVISION
 811 SOUTH FIRST
 ARTESIA, NEW MEXICO 88210

Line Enclosed*

Tony M.
 9327000554188

OF VIOLATION - Inactive Well(s)

De
 A rev
 time.
 than six
 or one ye
 must be tak

shut-in for an extended period of
 well may be shut-in no longer
 longer usable (e.g., a dry hole),
 regulations, corrective actions

[Handwritten signature]

- The detail sec
 The following op
1. Immediately
 2. Request Temp
 mechanical integrit
 3. Submit a proposa
 a timely basis after the

conduct a
 dures on
 date
 an
 ed

In the event that a satisfactory
 shown above, further enforcem
 order summoning you to a hearin,
 to permanently plug and abandon
 violation of OCD rules.

CANYON R & P COMPANY
 4925 GREENVILLE AVE.
 DALLAS, TX 75206

08 AUG 2016 PM
 LUBBOCK TX 79404

IDL

ARTESIA METEX
 UNIT 011

Inspection Date: 7/13/2016 9:19:51 AM
 Type Inspection: Routine/Periodic
 Comments on Inspection: Idle Well (Rule 201)
 LOCATION SIGN NC

ARTESIA METEX UNIT 023 N-19-18S-28E


INSURANCE
 UNABLE TO
 RETURN TO
 ADDRESSEE
 8210283411
 232-23369-08-03

08/09/2016 7:18 88210
 012E14642457
 \$0.09-405
 FIRST CLASS MAIL
 US POSTAGE

Inspection Date:	7/13/2016 9:41:53 AM	Corrective Action Due by:	10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales	Yes	No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VISIBLE. CONTAMINATED MATERIAL ON LOCATION	NO PJ.	CASING OUT OF GROUND
ARTESIA METEX UNIT 021	M-19-18S-28E	30-015-01942-00-00	Inspection No. iTM1619533198
Inspection Date:	7/13/2016 9:13:15 AM	Corrective Action Due by:	10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales	Yes	No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VISIBLE.	NO PJ.	CASING OUT OF GROUND
ARTESIA METEX UNIT 010	L-19-18S-28E	30-015-01943-00-00	Inspection No. iTM1619533964
Inspection Date:	7/13/2016 9:26:02 AM	Corrective Action Due by:	10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales	Yes	No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VISIBLE.	NO PJ.	CASING OUT OF GROUND
ARTESIA METEX UNIT 025	O-19-18S-28E	30-015-01946-00-00	Inspection No. iTM1619535680
Inspection Date:	7/13/2016 9:54:37 AM	Corrective Action Due by:	10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales	Yes	No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VISIBLE.	NO PJ.	CASING OUT OF GROUND
ARTESIA METEX UNIT 014	J-19-18S-28E	30-015-01947-00-00	Inspection No. iTM1619536694
Inspection Date:	7/13/2016 10:11:31 AM	Corrective Action Due by:	10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales	Yes	No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VISIBLE.	NO PJ.	CASING OUT OF GROUND
ARTESIA METEX UNIT 024	O-19-18S-28E	30-015-01949-00-00	Inspection No. iTM1619535377
Inspection Date:	7/13/2016 9:49:36 AM	Corrective Action Due by:	10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales	Yes	No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VISIBLE.	NO PJ.	CASING OUT OF GROUND
ARTESIA METEX UNIT 013	J-19-18S-28E	30-015-01951-00-00	Inspection No. iTM1619532178
Inspection Date:	7/13/2016 8:56:16 AM	Corrective Action Due by:	10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales	Yes	No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VISIBLE.	NO PJ.	CASING OUT OF GROUND
ARTESIA METEX UNIT 015	I-19-18S-28E	30-015-01954-00-00	Inspection No. iTM1619536207
Inspection Date:	7/13/2016 10:03:24 AM	Corrective Action Due by:	10/16/2016
Type Inspection	Inspector	Violation?	*Significant Non-Compliance?
Routine/Periodic	Tony Morales	Yes	No
Comments on Inspection:	Idle Well (Rule 201) LOCATION SIGN NOT VISIBLE.	NO PJ.	CASING OUT OF GROUND
ARTESIA METEX UNIT 012	K-19-18S-28E	30-015-01964-00-00	Inspection No. iTM1619532435

Thank you for your prompt attention to this matter and your efforts in helping to protect our environment and the infrastructure of the oil and gas industry.

Sincerely,



Artesia OCD District Office

* Significant Non-Compliance events are reported directly to the U.S. Environmental Protection Agency, Region VI, Dallas, Texas.