Submit One Copy To Appropriate District Office		ew Mexico	Form C-103
District I 1625 N. French Dr., Hobbs, NM 88240	Energy, Minerals a	nd Natural Resources	Revised November 3, 2011 WELL API NO.
District II	OU CONSERVA	ATION DIVISION	30-015-31889
811 S. First St., Artesia, NM 88210 District III		St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		NM 87505	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM	Salita PC,		6. State Oil & Gas Lease No.
87505			
(DO NOT USE THIS FORM FOR PROPOSA DIFFERENT RESERVOIR. USE "APPLICA"		N OR PLUG BACK TO A	7. Lease Name or Unit Agreement Name COTTON DRAW
PROPOSALS.) 1. Type of Well: Oil Well G	as Well 🕅 Other	the	8. Well Number 90
2. Name of Operator		MIN OF GANGENIE	9. OGRID Number
DEVON ENERGY PRODUCT 3. Address of Operator	TION CO LP C	En CIUA	6137 10. Pool name or Wildcat
PO BOX 250, ARTESIA, NM	88211	NN VELSS 3.0 50	PADUCA; DELAWARE
4. Well Location	·····	<u>9100 1510 100000000000000000000000000000</u>	
3. Address of Operator PO BOX 250, ARTESIA, NM 88211 Image: Constraint of the section of the se			
Section 36 Township 2	4S Range 31E NMA	County EDD	Y
	11. Elevation (Show whe	ther DR, RKB, RT, GR, etc.	
and the start of the second			
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data			
NOTICE OF INT		I SUB	SEQUENT REPORT OF:
-	PLUG AND ABANDON		
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DR	ILLING OPNS.
PULL OR ALTER CASING	MULTIPLE COMPL		IT JOB
OTHER:		Burled P&A	Marker Coordinates
All pits have been remediated in c		les and the terms of the Ope	erator's pit permit and closure plan.
	ed and leveled. Cathodic	les and the terms of the Ope protection holes have been	erator's pit permit and closure plan. properly abandoned.
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identification 	ed and leveled. Cathodic on marker plate is welded	les and the terms of the Ope protection holes have been to the top of the plugged w	erator's pit permit and closure plan. properly abandoned. rellhead, buried at least 3' below surface with
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identification GPS coordinates as follows: 32.179 	ed and leveled. Cathodic on marker plate is welded 2297; -103.7379303 N	les and the terms of the Ope protection holes have been to the top of the plugged w JAD83	erator's pit permit and closure plan. properly abandoned. vellhead, buried at least 3' below surface with
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identification GPS coordinates as follows: 32.179 It shows the OPERATOR NAME, LI 	ed and leveled. Cathodic on marker plate is welded (2297; -103.7379303 N EASE NAME, WELL N	les and the terms of the Ope protection holes have been to the top of the plugged w NAD83	erator's pit permit and closure plan. properly abandoned. rellhead, buried at least 3' below surface with
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identification GPS coordinates as follows: 32.179 It shows the OPERATOR NAME, LI 	ed and leveled. Cathodic on marker plate is welded (2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE.	les and the terms of the Ope protection holes have been to the top of the plugged w NAD83	erator's pit permit and closure plan. properly abandoned. yellhead, buried at least 3' below surface with OUARTER/OUARTER LOCATION OR
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identification GPS coordinates as follows: 32.179 It shows the <u>OPERATOR NAME, LI</u> <u>UNIT LETTER, SECTION, TOWN</u> <u>STAMPED ON THE MARKER'S S</u> 	ed and leveled. Cathodic on marker plate is welded 2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. URFACE.	les and the terms of the Ope protection holes have been to the top of the plugged w VAD83	erator's pit permit and closure plan. properly abandoned. /ellhead, buried at least 3' below surface with , <u>OUARTER/OUARTER LOCATION OR</u> BEEN WELDED OR PERMANENTLY
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identification GPS coordinates as follows: 32.179 It shows the OPERATOR NAME, LI UNIT LETTER, SECTION, TOWN STAMPED ON THE MARKER'S S The location has been leveled as r 	ed and leveled. Cathodic on marker plate is welded 2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. URFACE.	les and the terms of the Ope protection holes have been to the top of the plugged w VAD83	erator's pit permit and closure plan. properly abandoned. yellhead, buried at least 3' below surface with OUARTER/OUARTER LOCATION OR
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identificatio GPS coordinates as follows: 32.179 It shows the <u>OPERATOR NAME, LI</u> <u>UNIT LETTER, SECTION, TOWN</u> <u>STAMPED ON THE MARKER'S S</u> The location has been leveled as r other production equipment. Anchors, dead men, tie downs and 	ed and leveled. Cathodic on marker plate is welded (2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. URFACE. hearly as possible to orig: d risers have been cut off	les and the terms of the Ope protection holes have been to the top of the plugged w VAD83	erator's pit permit and closure plan. properly abandoned. /ellhead, buried at least 3' below surface with . OUARTER/OUARTER LOCATION OR BEEN WELDED OR PERMANENTLY s been cleared of all junk, trash, flow lines and und level.
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identification GPS coordinates as follows: 32.179 It shows the OPERATOR NAME, LI UNIT LETTER, SECTION, TOWN STAMPED ON THE MARKER'S S The location has been leveled as r other production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last reference 	ed and leveled. Cathodic on marker plate is welded (2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. (URFACE.) hearly as possible to orig: d risers have been cut off emaining well on lease, t	les and the terms of the Ope protection holes have been to the top of the plugged w VAD83 NUMBER, API NUMBER All INFORMATION HAS inal ground contour and has at least two feet below gro he battery and pit location(s	erator's pit permit and closure plan. properly abandoned. vellhead, buried at least 3' below surface with <u>OUARTER/OUARTER LOCATION OR</u> <u>BEEN WELDED OR PERMANENTLY</u> s been cleared of all junk, trash, flow lines and und level. s) have been remediated in compliance with
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identification GPS coordinates as follows: 32.179 It shows the OPERATOR NAME, LI UNIT LETTER, SECTION, TOWN STAMPED ON THE MARKER'S S The location has been leveled as r other production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operation 	ed and leveled. Cathodic on marker plate is welded (2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. (URFACE.) hearly as possible to orig: d risers have been cut off emaining well on lease, t	les and the terms of the Ope protection holes have been to the top of the plugged w VAD83 NUMBER, API NUMBER All INFORMATION HAS inal ground contour and has at least two feet below gro he battery and pit location(s	erator's pit permit and closure plan. properly abandoned. /ellhead, buried at least 3' below surface with . OUARTER/OUARTER LOCATION OR BEEN WELDED OR PERMANENTLY s been cleared of all junk, trash, flow lines and und level.
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identification GPS coordinates as follows: 32.179 It shows the OPERATOR NAME, LI UNIT LETTER, SECTION, TOWN STAMPED ON THE MARKER'S S The location has been leveled as r other production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operation 	ed and leveled. Cathodic on marker plate is welded 2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. URFACE. hearly as possible to origin d risers have been cut off emaining well on lease, t tor's pit permit and closu	les and the terms of the Ope protection holes have been to the top of the plugged w JAD83 <u>NUMBER, API NUMBER</u> All INFORMATION HAS inal ground contour and has at least two feet below gro he battery and pit location(s re plan. All flow lines, pro	erator's pit permit and closure plan. properly abandoned. vellhead, buried at least 3' below surface with <u>OUARTER/OUARTER LOCATION OR</u> <u>BEEN WELDED OR PERMANENTLY</u> s been cleared of all junk, trash, flow lines and und level. s) have been remediated in compliance with
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identification GPS coordinates as follows: 32.179 It shows the OPERATOR NAME, LI UNIT LETTER, SECTION, TOWN STAMPED ON THE MARKER'S S The location has been leveled as r other production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operation from lease and well location. All metal bolts and other materials to be removed.) 	ed and leveled. Cathodic on marker plate is welded 2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. URFACE. hearly as possible to origin d risers have been cut offic emaining well on lease, t tor's pit permit and closu s have been removed. Po	les and the terms of the Ope protection holes have been to the top of the plugged w VAD83 <u>NUMBER, API NUMBER</u> All INFORMATION HAS inal ground contour and has at least two feet below gro he battery and pit location(s re plan. All flow lines, pro	erator's pit permit and closure plan. properly abandoned. vellhead, buried at least 3' below surface with <u>OUARTER/OUARTER LOCATION OR</u> <u>BEEN WELDED OR PERMANENTLY</u> s been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identification GPS coordinates as follows: 32.179 It shows the OPERATOR NAME, LI UNIT LETTER, SECTION, TOWN STAMPED ON THE MARKER'S S The location has been leveled as r other production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operation from lease and well location. All metal bolts and other materials to be removed.) 	ed and leveled. Cathodic on marker plate is welded 2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. URFACE. hearly as possible to origin d risers have been cut offic emaining well on lease, t tor's pit permit and closu have been removed. Possible to be an addressed as	les and the terms of the Ope protection holes have been to the top of the plugged w JAD83 <u>UMBER, API NUMBER</u> All INFORMATION HAS inal ground contour and has at least two feet below gro he battery and pit location(s re plan. All flow lines, pro ortable bases have been rem per OCD rules.	erator's pit permit and closure plan. properly abandoned. vellhead, buried at least 3' below surface with <u>OUARTER/OUARTER LOCATION OR</u> <u>BEEN WELDED OR PERMANENTLY</u> s been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identificatio GPS coordinates as follows: 32.179 It shows the <u>OPERATOR NAME, LI</u> <u>UNIT LETTER, SECTION, TOWN</u> <u>STAMPED ON THE MARKER'S S</u> The location has been leveled as r other production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operat from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have been 	ed and leveled. Cathodic on marker plate is welded 2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. URFACE. hearly as possible to origin d risers have been cut offic emaining well on lease, t tor's pit permit and closu have been removed. Possible to be an addressed as	les and the terms of the Ope protection holes have been to the top of the plugged w JAD83 <u>UMBER, API NUMBER</u> All INFORMATION HAS inal ground contour and has at least two feet below gro he battery and pit location(s re plan. All flow lines, pro ortable bases have been rem per OCD rules.	erator's pit permit and closure plan. properly abandoned. vellhead, buried at least 3' below surface with <u>OUARTER/OUARTER LOCATION OR</u> <u>BEEN WELDED OR PERMANENTLY</u> s been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identificatio GPS coordinates as follows: 32.179 It shows the OPERATOR NAME, LI UNIT LETTER, SECTION, TOWN STAMPED ON THE MARKER'S S The location has been leveled as r other production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operat from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have beer retrieved flow lines and pipelines. 	ed and leveled. Cathodic on marker plate is welded 2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. URFACE. hearly as possible to orig: d risers have been cut off emaining well on lease, t for's pit permit and closu s have been removed. Po have been addressed as n abandoned in accordan	les and the terms of the Ope protection holes have been to the top of the plugged w VAD83	erator's pit permit and closure plan. properly abandoned. vellhead, buried at least 3' below surface with <u>OUARTER/QUARTER LOCATION OR</u> <u>BEEN WELDED OR PERMANENTLY</u> been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have C. All fluids have been removed from non-
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identificatio GPS coordinates as follows: 32.179 It shows the <u>OPERATOR NAME, LI</u> <u>UNIT LETTER, SECTION, TOWN</u> <u>STAMPED ON THE MARKER'S S</u> The location has been leveled as r other production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operat from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have beer retrieved flow lines and pipelines. If this is a one-well lease or last re 	ed and leveled. Cathodic on marker plate is welded (2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. A URFACE. hearly as possible to orig: d risers have been cut off emaining well on lease, t tor's pit permit and closu have been removed. Po have been addressed as n abandoned in accordan emaining well on lease: a on infrastructure.	les and the terms of the Ope protection holes have been to the top of the plugged w VAD83	erator's pit permit and closure plan. properly abandoned. vellhead, buried at least 3' below surface with <u>OUARTER/OUARTER LOCATION OR</u> <u>BEEN WELDED OR PERMANENTLY</u> been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- nd lines have been removed from lease and well
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identificatio GPS coordinates as follows: 32.179 It shows the <u>OPERATOR NAME, LI</u> <u>UNIT LETTER, SECTION, TOWN</u> <u>STAMPED ON THE MARKER'S S</u> The location has been leveled as r other production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operat from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have beer retrieved flow lines and pipelines. If this is a one-well lease or last re 	ed and leveled. Cathodic on marker plate is welded (2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. A URFACE. hearly as possible to orig: d risers have been cut off emaining well on lease, t tor's pit permit and closu have been removed. Po have been addressed as n abandoned in accordan emaining well on lease: a on infrastructure.	les and the terms of the Ope protection holes have been to the top of the plugged w VAD83	erator's pit permit and closure plan. properly abandoned. vellhead, buried at least 3' below surface with <u>OUARTER/OUARTER LOCATION OR</u> <u>BEEN WELDED OR PERMANENTLY</u> been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- nd lines have been removed from lease and well
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identificatio GPS coordinates as follows: 32.179 It shows the <u>OPERATOR NAME, LI</u> <u>UNIT LETTER, SECTION, TOWN</u> <u>STAMPED ON THE MARKER'S S</u> The location has been leveled as r other production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operat from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have beer retrieved flow lines and pipelines. If this is a one-well lease or last re 	ed and leveled. Cathodic on marker plate is welded 2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. A URFACE. hearly as possible to orig: d risers have been cut off emaining well on tease, t tor's pit permit and closu s have been removed. Po a have been addressed as n abandoned in accordan emaining well on lease: a on infrastructure. turn this form to the appr	les and the terms of the Ope protection holes have been to the top of the plugged w VAD83	erator's pit permit and closure plan. properly abandoned. vellhead, buried at least 3' below surface with <u>OUARTER/OUARTER LOCATION OR</u> <u>BEEN WELDED OR PERMANENTLY</u> been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- nd lines have been removed from lease and well
 All pits have been remediated in complete the second state of the second stat	ed and leveled. Cathodic on marker plate is welded 2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. A URFACE. hearly as possible to orig: d risers have been cut off emaining well on lease, t tor's pit permit and closu s have been removed. Po a have been addressed as n abandoned in accordan emaining well on lease: a on infrastructure. turn this form to the appr Yenger T	les and the terms of the Ope protection holes have been to the top of the plugged w VAD83	erator's pit permit and closure plan. properly abandoned. vellhead, buried at least 3' below surface with <u>OUARTER/OUARTER LOCATION OR</u> <u>BEEN WELDED OR PERMANENTLY</u> been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- nd lines have been removed from lease and well hedule an inspection. JPPORTDATE8/30/2016
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identification GPS coordinates as follows: 32.179 It shows the OPERATOR NAME, LI UNIT LETTER, SECTION, TOWN STAMPED ON THE MARKER'S S The location has been leveled as rother production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operation lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have been retrieved flow lines and pipelines. If this is a one-well lease or last re location, except for utility's distribution. 	ed and leveled. Cathodic on marker plate is welded 2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. A URFACE. hearly as possible to orig: d risers have been cut off emaining well on lease, t tor's pit permit and closu s have been removed. Po a have been addressed as n abandoned in accordan emaining well on lease: a on infrastructure. turn this form to the appr Yenger T	les and the terms of the Ope protection holes have been to the top of the plugged w VAD83	erator's pit permit and closure plan. properly abandoned. vellhead, buried at least 3' below surface with <u>OUARTER/OUARTER LOCATION OR</u> <u>BEEN WELDED OR PERMANENTLY</u> been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- nd lines have been removed from lease and well hedule an inspection. JPPORTDATE8/30/2016
 All pits have been remediated in c Rat hole and cellar have been fille A steel below ground identificatio GPS coordinates as follows: 32.179 It shows the OPERATOR NAME, LI UNIT LETTER, SECTION, TOWN STAMPED ON THE MARKER'S S The location has been leveled as r other production equipment. Anchors, dead men, tie downs and If this is a one-well lease or last re OCD rules and the terms of the Operation from lease and well location. All metal bolts and other materials to be removed.) All other environmental concerns Pipelines and flow lines have been retrieved flow lines and pipelines. If this is a one-well lease or last relocation, except for utility's distribution. SIGNATURE August Angle August Augus	ed and leveled. Cathodic on marker plate is welded 2297; -103.7379303 N EASE NAME, WELL N SHIP, AND RANGE. URFACE. hearly as possible to origin d risers have been cut off emaining well on lease, t tor's pit permit and closu shave been addressed as n abandoned in accordan emaining well on lease: a on infrastructure. turn this form to the appr Menoud E-MAIL: de	les and the terms of the Ope protection holes have been to the top of the plugged w VAD83	erator's pit permit and closure plan. properly abandoned. vellhead, buried at least 3' below surface with <u>OUARTER/OUARTER LOCATION OR</u> <u>BEEN WELDED OR PERMANENTLY</u> been cleared of all junk, trash, flow lines and und level. b) have been remediated in compliance with duction equipment and junk have been removed oved. (Poured onsite concrete bases do not have C. All fluids have been removed from non- nd lines have been removed from lease and well hedule an inspection. JPPORTDATE8/30/2016 PHONE:575-746-5544

ľ,

Conditions of Approval (if any):

, ·

^ .