

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

**NM OIL CONSERVATION**

ARTESIA DISTRICT

Form C-141

Revised August 8, 2011

SEP 07 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

NAB1625342050 OPERATOR  Initial Report  Final Report

Name of Company	Oxy Permian Ltd. <u>110096</u>	Contact	Casey Summers
Address	6 Desta Drive, Midland, TX 79705	Telephone No.	(575) 513-8289
Facility Name	Harroun 15 #3 & #5 CTB	Facility Type	Battery
Surface Owner	BLM	Mineral Owner	API No. 30-015-29233

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
H	15	24S	29E					Eddy County, NM

Latitude N 32.22011° Longitude W 103.96463°

**NATURE OF RELEASE**

Type of Release	Oil and Produced water	Volume of Release	3 bbls oil, 7 bbls produced water	Volume Recovered	9 bbls
Source of Release	Compromised 2" steel line from the separator	Date and Hour of Occurrence	08/22/2016	Date and Hour of Discovery	
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	Mike Bratcher, Heather Patterson- NMOCD; Shelly Tucker- BLM		
By Whom?	Kathy Purvis @ BBC International Inc.	Date and Hour	08/23/2016 @ 4:54 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.\*



Describe Cause of Problem and Remedial Action Taken.\*

A compromised 2" steel line from the separator leaked 3 bbls of oil and 7 bbls of produced water. A vacuum truck recovered 9 bbls of fluids and the line was repaired.

Describe Area Affected and Cleanup Action Taken.\*

The affected area is approximately 10' x 20' both on and off location. Remediation will be completed in accordance with an approved remediation plan from NMOCD and the BLM.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		<b>OIL CONSERVATION DIVISION</b>	
Printed Name:	Casey Summers	Approved by Environmental Specialist:	
Title:	NM Environmental Advisor	Approval Date:	9/8/16
E-mail Address:	Casey_Summers@oxy.com	Expiration Date:	N/A
Date:	9-7-16	Phone:	(575) 513-8289
		Conditions of Approval:	Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>
		<b>118111 REMEDIATION PROPOSAL NO</b>	

\* Attach Additional Sheets If Necessary

THAN: 10/11/16

2RP-3878