

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

ARTESIA DISTRICT

SEP 13 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Form C-141
Revised August 8, 2011

Release Notification and Corrective Action

NAB1625930251

274341

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Rover Operating, LLC	Contact	Kirk Faries
Address	13727 Noel rd. Tower 2 Suite 200 Dallas, TX 75240	Telephone No.	575-513-3198
Facility Name	Atsel Leonard Federal	Facility Type	oil production

Surface Owner	BLM	Mineral Owner	Rover Operating LLC	API No.	N/A
---------------	-----	---------------	---------------------	---------	-----

30-015-03191

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
J	30	17S	29E					EDDY

Latitude _____ Longitude _____

NATURE OF RELEASE

Soil 10PW

Type of Release	OIL & SALT WATER	Volume of Release	35 BBLS	Volume Recovered	15 BBLS
Source of Release	BROKEN WATER LEG ON VESSEL	Date and Hour of Occurrence	9-12-16 APPROX. 4 PM	Date and Hour of Discovery	9-12-16 APPROX. 5 PM
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? CALLED BLM & NMOCD AND LEFT MESSAGES AFTER HOURS, THEN PHONE CALLS NEXT MORNING			
By Whom?	KIRK FARIES (PRODUCTION FOREMAN)	Date and Hour	9-12-16 APPROX. 6 PM		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.			

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken.*

STORM CAME THROUGH HIGH WINDS CAUSED WATER LEG ON VESSEL TO BREAK RELEASING FLUID. RETRIEVED AS MUCH FLUID AS POSSIBLE HAULED TO DISPOSAL. NEXT DAY NOTIFY BLM & NMOCD ON PHONE GOT PERMISSION TO START REMOVING CONTAMINATED SOIL TO PLASTIC LINER. ONCE SOIL IS REMOVED SAMPLES WILL BE TAKEN TO CARDINAL LABS IN HOBBS, NM. ONCE ALL CONTAMINATION IS REMOVED AND PROPERLY DISPOSED OF WE WILL BACKFILL WITH PROPER SOIL AND RESEED IF NECESSARY. ALL REPAIRS WILL BE MADE TO BATTERY AND BURM BUILT. ALL PAPERWORK WILL BE FILED ACCORDINGLY.

Describe Area Affected and Cleanup Action Taken.*

AFFECTED AT BATTERY THEN RUNS APPROX. 105' SOUTHEAST TO CALICHE ROAD THEN 330' SOUTH ON ROAD. 15 BBLS RECOVERED NIGHT OF SPILL, START REMOVING CONTAMINATED SOIL TO PLASTIC LINER AS OF THIS REPORT.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: KIRK FARIES		OIL CONSERVATION DIVISION	
Printed Name: KIRK FARIES		Approved by Environmental Specialist: Signed By: <i>[Signature]</i>	
Title: PRODUCTION FOREMAN		Approval Date: 9/15/16	Expiration Date: N/A
E-mail Address: kfaries@roverpetro.com		Conditions of Approval:	
Date: 9-13-2016	Phone: 575-513-3198	Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/> SUBMIT REMEDIATION PROPOSAL NO LATER THAN: 10/15/16	

* Attach Additional Sheets If Necessary

2RP-3885