

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

SEP 15 2016

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

RECEIVED

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Release Notification and Corrective Action

NAB/02/0342939

OPERATOR Initial Report Final Report

Name of Company Devon Energy Production Company <i>6137</i>	Contact Jake Harrington, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 432-214-5175
Facility Name Cotton Draw Unit #153H	Facility Type Oil

Surface Owner Federal	Mineral Owner Federal	API No 30-015-38535
------------------------------	------------------------------	----------------------------

LOCATION OF RELEASE

Unit Letter B	Section 3	Township 25S	Range 31E	Feet from the 200	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude: 32.1661758 **Longitude:** -103.7636108

NATURE OF RELEASE

Type of Release Produced water	Volume of Release 42 Gallons	Volume Recovered 39 Gallons
Source of Release Transfer pump	Date and Hour of Occurrence 9/14/2016 @ 11:45pm	Date and Hour of Discovery 9/14/2016 @ 11:45pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? OCD-Mike Bratcher BLM-Jim Amos	
By Whom? Lolo Martinez, Lease Operator	Date and Hour OCD- 9/15/2016 @ 1:15am BLM- 9/15/2016 @ 1:20am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	

If a Watercourse was Impacted, Describe Fully.* N/A

Describe Cause of Problem and Remedial Action Taken.*

Due to corrosion on the swage on the discharge side of the transfer pump 42 gallons of produce water was released. The well and water injection pump was shut down immediately to prevent further release. Repairs to the swage on discharge pump are in progress.

Describe Area Affected and Cleanup Action Taken.*

42 gallons of produced water was released from a corroded swage on the discharge pump that runs from the produced water tank. Approximately 39 gallons went into lined containment and 3 gallons sprayed into a Westerly direction into the pasture. The approximate area affected was 6ft x 6ft in the pasture West of water injection pump. Approximately 3 gallons of the released produced water sprayed in a Westerly direction away from the pad into the pasture. The liner was checked for holes, no holes were found. Vacuum truck recovered approximately 39 gallons of the released produced water. Environmental agency will be contacted for remediation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Sarah Gallegos-Troublefield	OIL CONSERVATION DIVISION	
Printed Name: Sarah Gallegos-Troublefield	Signed By <i>Mike Bratcher</i>	
Title: Field Admin Support	Approved by Environmental Specialist:	
E-mail Address: Sarah.Gallegos-Troublefield@dvn.com	Approval Date: <i>9/19/16</i>	Expiration Date: <i>N/A</i>
Date: 9/15/2016 Phone: 575.748.1864	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary

SUBMIT REMEDIATION PROPOSAL NO
LATER THAN: *10/22/16*

2 RP-3892