

NM OIL CONSERVATION

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

ARTESIA DISTRICT

OCT 05 2016

RECEIVED

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division

1220 South St. Francis Dr.

Santa Fe, NM 87505

Form C-141
Revised August 8, 2011Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.**Release Notification and Corrective Action****OPERATOR**☐ Initial Report ☒ Final Report

Name of Company LINN Energy	Contact EL Gonzales
Address 2130 W. Bender Blvd. Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name J L Keel-A #14	Facility Type Injection Well

Surface Owner BLM	Mineral Owner Fed. Gov't	API No.30-015-05102
-------------------	--------------------------	---------------------

LOCATION OF RELEASE

Unit Letter D	Section 7	Township 17S	Range 31E	Feet from the 660'	North/South Line South	Feet from the 579'	East/West Line West	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.84544159 Longitude -103.9152679



NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 77 BBLS	Volume Recovered 0 BBLS
Source of Release Injection Line	Date and Hour of Occurrence 10/6/11	Date and Hour of Discovery 10/6/11 4:00 pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Terry Gregston (BLM) and Mike Bratcher OCD	
By Whom? Joe Hernandez	Date and Hour 10/7/11 9:00 am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

Describe Cause of Problem and Remedial Action Taken *
Injection Leak on 2" H. P. Fiberglass line. Shut line off.Describe Area Affected and Cleanup Action Taken.*
19000 sq. ft.
Remediation complete

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: E. L. Gonzales	Approved by Environmental Specialist: 	
Title: Production Supervisor	Approval Date: 10/7/16	Expiration Date: N/A
E-mail Address: ELgonzaless@linnenergy.com	Conditions of Approval: Final	Attached <input type="checkbox"/>
Date: 8/30/16	Phone: (575) 738-1739	

* Attach Additional Sheets If Necessary

2RP-929