

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

OCT 11 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

RECEIVED Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB 1128854810

OPERATOR

X Initial Report Final Report

Name of Company Lime Rock Resources II-A, L.P. <i>227558</i>	Contact Mike Barrett
Address R347-2 North 26 Street, Artesia, New Mexico 88210	Telephone No. 505-353-2644
Facility Name ASAU 149 Trunk line release	

Surface Owner Fee	Mineral Owner State	API No. 30-015-00204
-------------------	---------------------	----------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
O	14	18S	26E	990	FSL	1650	FEL	EDDY

Latitude 32.74266 Longitude 104.34846

NATURE OF RELEASE

Type of Release Hydrocarbon, produced waters. gas	Volume of Release unknown	Volume Recovered 0 bbls
Source of Release production line	Date and Hour of Occurrence 9/30/2016 am	Date and Hour of Discovery 9/30/2016 am
Was Immediate Notice Given? Yes No X The release is thought to be less than 25 bbls	If YES, To Whom?	
By Whom? Mike Barrett	Date and Hour Voice Message to Heather Patterson on 10/3	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Full

Describe Cause of Problem and Remedial Action Taken.*
A 3" below grade FG flow line developed a leak due to corrosion, the line was immediately shut-in, and the line was excavated and then repaired. The volume of the release caused by the below grade flow line was unknown.

Describe Area Affected and Cleanup Action Taken.*
The area affected by the release is on the west side of Fanning road (CR-44) and was measured to be 15' along the pipe. Evaluation is ongoing to determine if the release was in such quantity as may with reasonable probability be detrimental to water or exceed the standards in Subsections A and B or C of 19.15.30.9 NMAC. Lime Rock will provide the results of the ongoing investigations to OCD and, if necessary, a remediation plan consistent with Part 29.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

AMENDED	OIL CONSERVATION DIVISION	
Signature: <i>Michael Barrett</i>	Signed By <i>Mike Barrett</i> Approved by Environmental Specialist.	
Printed Name: Michael Barrett	Approval Date: <i>10/14/16</i>	Expiration Date: <i>N/A</i>
Title: Production Superintendent	Conditions of Approval: Remediation per O.C.D. Rules & Guidelines <input type="checkbox"/>	
E-mail Address: Michael Barrett <mbarrett@limerockresources.com>	SUBMIT REMEDIATION PROPOSAL NO	
Date: 10/7/2016 Phone: 505-353-2644	LATER THAN: <u>11/14/16</u>	

* Attach Additional Sheets If Necessary

ARD-3940