

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

NM OIL CONSERVATION

ARTESIA DISTRICT

NOV 10 2016

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

RECEIVED

Release Notification and Corrective Action

NAB1631930558 OPERATOR Initial Report Final Report


Name of Company: BOPCO, L.P. 260737	Contact: Bradley Blevins
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No. 575-887-7329
Facility Name: Poker Lake CVX JV BS 017H	Facility Type: Exploration and Production
Surface Owner: Federal	Mineral Owner:
API No. 3001540447	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	7	25S	31E	150		1980		Eddy

Latitude: 32.15249 Longitude: 103.81916

NATURE OF RELEASE

Type of Release: Produced Water	Volume of Release: 31 barrels	Volume Recovered: 20 barrels
Source of Release: Steel riser on SWD line	Date and Hour of Occurrence: 11-10-16 @ 9:30am	Date and Hour of Discovery: 11-10-16 @ 10:00am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Via C-141. Mike Bratcher, Heather Patterson, Jim Amos BLM	
By Whom? Bradley Blevins	Date and Hour: 11-11-16 @ 8:40am	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	
If a Watercourse was Impacted, Describe Fully.*		
Describe Cause of Problem and Remedial Action Taken.* EH&S was notified of a release at the PLU Big Sinks 7-25-31 Battery. Release was caused by a hole that developed in the steel riser of the SWD line on the north side of the battery containment. Vacuum truck was called to the location and recovered 20 barrels of produced water		
Describe Area Affected and Cleanup Action Taken.* Release affected an area on the north side of the battery containment; a vacuum truck was utilized to recover 20 barrels of produced water from the ground surface.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 		OIL CONSERVATION DIVISION
Printed Name: Bradley Blevins		Approved by Environmental Specialist: 
Title: Assistant Remediation Foreman	Approval Date: 11/14/16	Expiration Date: N/A
E-mail Address: bblevins@basspet.com	Conditions of Approval:	Attached <input checked="" type="checkbox"/>
Date: 11/11/16	Phone: 432-214-3704	

* Attach Additional Sheets If Necessary

2RP-3985