

NOV 30 2016

Form C-141  
Revised August 8, 2011

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in  
conformance with 19.15.29 NMAC.

RECEIVED

**Release Notification and Corrective Action**

*NAB11034038388*

**OPERATOR**

Initial Report  Final Report

Name of Company: <b>COG Operating LLC</b> <i>229137</i>	Contact: <b>Robert McNeill</b>
Address: <b>600 West Illinois Avenue, Midland TX 79701</b>	Telephone No. <b>432-683-7443</b>
Facility Name: <b>Firefox 4 Fed Com 5H Battery</b>	Facility Type: <b>Tank Battery</b>

Surface Owner: <b>Federal</b>	Mineral Owner:	API No. <b>30-015-41423</b>
-------------------------------	----------------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
M	04	19S	31E	670	South	250	West	Eddy

Latitude 32.684082 Longitude 103.8822098

**NATURE OF RELEASE**

Type of Release: <b>Produced Water</b>	Volume of Release: <b>8bbbls</b>	Volume Recovered: <b>7bbbls</b>
Source of Release: <b>Water Line</b>	Date and Hour of Occurrence: <b>November 25, 2016 10:00 am</b>	Date and Hour of Discovery: <b>November 25, 2016 10:00 am</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour:	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

Describe Cause of Problem and Remedial Action Taken.\*

A four (4) inch 45 degree fitting on a water line developed a hole. The 45 degree fitting was replaced.

Describe Area Affected and Cleanup Action Taken.\*

The release occurred on location but outside the battery berm. A vacuum truck was dispatched to remove all freestanding fluids. Concho will have the spill area sampled to delineate any possible impact from the release and we will present a remediation work plan to the NMOCD for approval prior to any significant remediation activities.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Rebecca Haskell</i>	<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <b>Rebecca Haskell</b>	Signed By <i>Mike [Signature]</i>	
Title: <b>Senior HSE Coordinator</b>	Approved by Environmental Specialist:	
E-mail Address: <b>rhaskell@concho.com</b>	Approval Date: <b>11/30/16</b>	Expiration Date: <b>NA</b>
Date: <b>11/30/16</b> Phone: <b>432-683-7443</b>	Conditions of Approval:	Attached <input checked="" type="checkbox"/>

\* Attach Additional Sheets If Necessary

*ARD 4024*