Form 3160-5 (June 2015)	UNITED STATE		OCD Artesia	-	OMB NO	APPROVED D. 1004-0137		
BI	PARTMENT OF THE UREAU OF LAND MAN.	AGEMENT		4	Expires: Ja 5. Lease Serial No.	nuary 31, 2018		
SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.					NMNM0557371 6. If Indian, Allottee or Tribe Name			
SUBMIT IN TRIPLICATE - Other instructions on page 2					<ol> <li>If Unit or CA/Agreement, Name and/or No.</li> <li>8. Well Name and No.</li> </ol>			
1. Type of Well								
🛛 Oil Well 🗖 Gas Well 🗖 Oth	AAO FEDERAL 005 9. API Well No.							
2. Name of Operator APACHE CORP	E-Mail: Isabel.Hu	ISABEL HU	DSON corp.com		9. API well No. 30-015-32959			
3a. Address3b. Phone N303 VETERANS AIRPARK LANE SUITE 1000Ph: 432-8MIDLAND, TX 79705Ph: 432-8						10. Field and Pool or Exploratory Area RDLK;GLO-YSO,NE,QN,GRA-SA		
4. Location of Well (Footage, Sec., 7		11. County or Parish, State						
Sec 1 T18S R27E 1650FNL 875FWL					EDDY COUNTY, NM			
12. CHECK THE AI	PPROPRIATE BOX(ES	) TO INDICA	TE NATURE OF	NOTICE	, REPORT, OR OTI	ÆR DATA		
TYPE OF SUBMISSION			TYPE OF	ACTION	NC			
Notice of Intent	🗖 Acidize	De	epen	Produc	tion (Start/Resume)	U Water S	hut-Off	
	Alter Casing	🗖 Hy	draulic Fracturing	🗖 Reclan	nation	🗖 Well Int	egrity	
Subsequent Report	🗖 Casing Repair		v Construction 🔲 Recom			D Other		
Final Abandonment Notice				mporarily Abandon				
	Convert to Injection		g Back	U Water				
13. Describe Proposed or Completed Op If the proposal is to deepen direction. Attach the Bond under which the wo following completion of the involved testing has been completed. Final Al determined that the site is ready for f	ally or recomplete horizontall rk will be performed or provid operations. If the operation bandonment Notices must be	y, give subsurface le the Bond No. c results in a multi	e locations and measur on file with BLM/BIA.	ed and true v Required sumpletion in a	vertical depths of all pertinu ubsequent reports must be new interval a Form 316	nent markers an filed within 30 50-4 must be fil	d zones. days ed once	
Apache would like to perform	the following work. (Plea	ase see attach	iments)			L CONSE		
Production Casing: 5-1/2? 17 Producing Interval: 2,131-3,65		arthua district FFP <b>1 3</b> 2017						
Objective: Isolate open perfs a shallower zone. Geological an before a re-completion is prop	id Petrophysical analysi	eing evaluateo s are being pe	l for recompletion rformed. More tim	potential ir le is neede	n a ed	RECEIVE	-C)	
before a re-completion is prop		Accepted	for record		SEE ATTACL			
Procedure:		NM	DCD 2/13/17	7	SEE ATTACHED FOR			
1. POOH with rods and tbg		PI	•4••1		CONDITIONS	S OF API	PRO	
14. I hereby certify that the foregoing is			<u> </u>				<u> </u>	
	Electronic Submission For A	PACHE CORP,	sent to the Carlsb	ad	•			
Name (Printed/Tuned) ICADEL 1	Committed to AFMSS fo	r processing b						
Name (Printed/Typed)  SABEL	10050N		Title REGUL/	ATORY AN	VALISI	<u></u>		
Signature (Electronic S	Submission)		Date 01/04/20	)17				
	THIS SPACE F	OR FEDER	AL OR STATE (	OFFICE U	JSE			
Approved By	O. Dom	?	Title _	PET	Τ	Z. Date	. 7-1	
Conditions of approval, if any, are attached ertify that the applicant holds legal or equivich would entitle the applicant to condu- which would entitle the applicant to condu-	itable title to those rights in t	es not warrant or he subject lease	Office C	(FD				
itle 18 U.S.C. Section 1001 and Title 43 States any false, fictitious or fraudulent s	U.S.C. Section 1212, make it statements or representations	a crime for any p as to any matter v	erson knowingly and vithin its jurisdiction.	willfully to m	nake to any department of	agency of the I	Jnited	

•

(Instructions on page 2) \*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\* OPERATOR-SUBMITTED \*\*

## Additional data for EC transaction #362839 that would not fit on the form

## 32. Additional remarks, continued

.

- Scan tbg and mark junk pipe
   Set CIBP @ 2,100? and dump bail 35? of cmt
   Fill casing with fluid and pressure test to 500 psi
   Record the test on a chart and submit for approval

January 4, 2017

· •

AAO Federal # 5 API # 30-015-32959 Eddy County, NM Production Casing: 5-1/2" 17# @ 3,892' Producing Interval: **2,131-3,658**'

**<u>Objective</u>**: Isolate open perfs and TA wellbore. Well being evaluated for recompletion potential in a shallower zone. Geological and Petrophysical analysis are being performed. More time is needed before a re-completion is proposed.

# Procedure:

- 1. POOH with rods and tbg
- 2. Scan tbg and mark junk pipe
- 3. Set CIBP @ 2,100' and dump bail 35' of cmt
- 4. Fill casing with fluid and pressure test to 500 psi
- 5. Record the test on a chart and submit for approval

GROUP: FIELD: LEASE/UNIT: COUNTY: API:	Permian North Red Lake NE (BP) AAO Federal Eddy 30-015-32959	DATE: BY: WELL: STATE:	Oct. 31, 2013 Lucas Emmett 5 New Mexico
Spud Date: 11 Rig Release D Completion Da UL-E, Section-	ate: 11/10/03 te: 2/10/04 1, T-18S, R-27E	KB = GL = 361	5'
		" Hole) set @ 357' w/ 300 sx - ' Hole) set @ 3892' w/ 800 sx - '	
San Andres	Yeso/Glorieta: 2/3/04: Perf 3380', 3385', 3539', 3569', 3590', 3597 2/4/04: Frac w/113930# S PAD, 5k gal gel w/.25# g	3395, 3399', 3415', 3423', 345( ', 3621', 3626', 3658' (20 Shot) Sand & 2580 BBLs Fluid as foll al 20/40 Brown, 7k gal gel 2/.5 <del>5</del> 5k gal 2#/gal 20/40, 5k gal gel /	- acdz w/ 200 gal 15% HC ows: 19K gal fw PAD, 3H #gal 20/40, 30k gal gel w/
		0'. Perf the Upper San Andres ( 95, 2522, 29, 37, 2625, 85, 93, ' wab Test.	
		San Andres w/ 187,554 gal slurr A. Average prop concentration 2 np.	
Yeso/ Glorieta	Production Allocation: (3 Redlake Q-GR-SA 51300 Redlake Glorieta/Yeso N		

· •

#### BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

### Temporary Abandonment of Wells on Federal Lands Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

- 1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
- 2. A description of the temporary abandonment procedure.

a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. The bridge plug is to be capped with 35 feet of cement (if bailed) or 25 sacks (if placed with tubing). If a cement plug is used, the top of the cement must be verified by tagging.

b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes with a 10% allowable leakoff.

c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.

d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.

e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.

#### 3. Provides justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned.

Wells that successfully pass the casing integrity test may be approved for Temporary Abandonment (TA) status provided that the operator:

- 1. Submits a subsequent Sundry Notice (Form 3160-5) requesting TA approval with well bore diagram.
- 2. Describes the temporary abandonment procedure.
- 3. Attaches a clear copy or the original of the pressure test chart.
- 4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

- 1. A procedure to repair the casing so that a TA approval can be granted.
- 2. A procedure to plug and abandon the well.

Well Name: Submit Subsequent Report and well bore diagram with all Perforations and CIBP with tops of cement. Well may be approved to be TA for a period of 1 year after successful MIT and subsequent report is submitted.