



PHONE (325) 873-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2326 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR  
FASKEN OIL & RANCH LTD  
ATTN: DOUG LITTLE  
303 W. WALL STE. 1800  
MIDLAND, TX 79701  
FAX TO: (432) 687-1570

Receiving Date: 03/22/06  
Reporting Date: 03/27/06  
Project Number: NOT GIVEN  
Project Name: PECOS 36 ST #1  
Project Location: EDDY COUNTY, NM

Sampling Date: 03/23/06  
Sample Type: SOIL  
Sample Condition: COOL & INTACT  
Sample Received By: AH  
Analyzed By: BC/AB

30-015-32722  
Samples From P.t. AREA


LAB NUMBER	SAMPLE ID	TPH (mg/Kg)	CI (mg/Kg)
ANALYSIS DATE:		03/23/06	03/23/06
H10922-1	1	344	3199
H10922-2	2	297	3199
H10922-3	3	199	1200
H10922-4	4	190	800
H10922-5	5	47.9	1999
Quality Control		227	500
True Value QC		240	500
% Recovery		94.5	100
Relative Percent Difference		5.6	2

RECEIVED

MAR 31 2006

ODU-ARTEDIA

METHODS: TPH-EPA 600/4-79-020 418.1; CI-Std. Methods 4500-CIB

  
Chemist

  
Date

H10922

LEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses. If claims, including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profit incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.



# ARDINAL LABORATORIES

PHONE (325) 873-7001 • 2111 BEECHWOOD • ABILENE, TX 79603

PHONE (505) 393-2328 • 101 E. MARLAND • HOBBS, NM 88240

ANALYTICAL RESULTS FOR  
FASKEN OIL & RANCH LTD  
ATTN: DOUG LITTLE  
303 WEST WALL STE. 1800  
MIDLAND, TX 79701  
FAX TO: 432-687-1570

Receiving Date: 3/22/06  
Reporting Date: 3/27/06  
Project Number: NONE GIVEN  
Project Name: PECOS 36 ST #1  
Project Location: EDDY COUNTY

Sampling Date: 3/23/06  
Sample Type: SOIL  
Sample Condition: COOL & INTACT  
Sample Received By: AH  
Analyzed By: JC

LAB NUMBER	SAMPLE ID	BENZENE (mg/kg)	TOLUENE (mg/kg)	ETHYLBENZENE (mg/kg)	TOTAL XYLENES (mg/kg)
ANALYSIS DATE:		3/25/2006	3/25/2006	3/25/2006	3/25/2006
H10922-1	1	<0.002	<0.002	<0.002	<0.006
H10922-2	2	0.003	<0.002	<0.002	<0.006
H10922-3	3	<0.002	<0.002	<0.002	<0.006
H10922-4	4	<0.002	<0.002	<0.002	<0.006
H10922-5	5	<0.002	<0.002	<0.002	<0.006
Quality Control		0.095	0.093	0.092	0.273
True Value QC		0.100	0.100	0.100	0.300
% Recovery		95	93	92	91
Relative Percent Difference		4.8	1.2	1.3	7.9

METHODS: EPA - SW 846-8021B, 5030B; Gas Chromatography

RECEIVED

MAR 31 2006

DOUG LITTLE

Chemist

3/27/06  
Date

PLEASE NOTE: Liability and Damages. Cardinal's liability and client's exclusive remedy for any claim arising, whether based in contract or tort, shall be limited to the amount paid by client for analyses and claims. Including those for negligence and any other cause whatsoever shall be deemed waived unless made in writing and received by Cardinal within thirty (30) days after completion of the applicable service. In no event shall Cardinal be liable for incidental or consequential damages, including, without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above-stated reasons or otherwise.