## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez


Governor

Ken McQueen Cabinet Secretary

**Matthias Saver** 

**Deputy Cabinet Secretary** 

**David Catanach** Division Director





## \*Response Required - Deadline Enclosed\*

Field Inspection Program "Preserving the Integrity of Our Environment"

23-May-17

## J CLEO THOMPSON

P.O. BOX 12577 ODESSA TX 79768

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

INSPECTION DETAIL SECTION
---------------------------

WEST SQUARE LAKE UNIT No.014 I-4-17S-30E 30-015-04082-00-00 \*Significant Corrective Inspection Violation? Inspection No. Type Inspection Inspector Non-Compliance? Action Due By: Date iTM1714342452 05/23/2017 Routine/Periodic **Tony Morales** Yes No 8/26/2017 **Violations** General Housekeeping (Rule 114)

OK. All Equipment and Location in Good Shae. PJ. STAINING AROUND WELL HEAD. **Comments on Inspection:** RULE 19.15.35.7B

WEST SQUARE LAKE UNIT No.015 O-4-17S-30E 30-015-04083-00-00 \*Significant Corrective Inspection Type Inspection Inspector Violation? Inspection No. Non-Compliance? Action Due By: Date 8/26/2017 iTM1714344073 05/23/2017 Routine/Periodic **Tony Morales** Yes No **Violations** 

General Housekeeping (Rule 114)

OK. All Equipment and Location in Good Shape. PJ STAINING AROUND WELL HEAD. Comments on Inspection:

POWER OFF RULE 19.15.35.7B

## WEST SQUARE LAKE UNIT No.016

P-4-17S-30E

30-015-04084-00-00

Inspection

**Type Inspection** 

Inspector

Violation?

\*Significant Non-Compliance? Corrective

Date 05/23/2017

Routine/Periodic

Tony Morales

Yes

No

**Action Due By:** 8/26/2017

Inspection No. iTM1714341927

**Violations** 

General Housekeeping (Rule 114)

**Comments on Inspection:** 

OK. All Equipment and Location in Good Shape. PJ. STAINING AROUND WELLHEAD+

CALICHE STOCK PILE ON LOCATION. WRONG WELL NUMBER

WEST SQUARE LAKE UNIT No.015

N-4-17S-30E

30-015-04087-00-00

Inspection

Type Inspection Date

Inspector

Violation?

\*Significant Non-Compliance?

Corrective Action Due By:

Inspection No.

05/23/2017

Routine/Periodic

**Tony Morales** 

Yes

No

8/26/2017

iTM1714344777

**Violations** 

General Housekeeping (Rule 114)

**Comments on Inspection:** 

OK. All Equipment an Location in Good Shape. PJ. STAINING AROUND WELL HEAD+.

DOWN LEASE ROAD. RULE 19.15.35.7B

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. \*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.