

NM OIL CONSERVATION

ARTESIA DISTRICT

 State of New Mexico
 Energy Minerals and Natural Resources

MAY 12 2017

 Form C-141
 Revised August 8, 2011

 District I
 1625 N. French Dr., Hobbs, NM 88240
 District II
 811 S. First St., Artesia, NM 88210
 District III
 1000 Rio Brazos Road, Aztec, NM 87410
 District IV
 1220 S. St. Francis Dr., Santa Fe, NM 87505

 Oil Conservation Division
 1220 South St. Francis Dr.
 Santa Fe, NM 87505

 Submit 1 Copy to appropriate District Office in
 accordance with 19.15.29 NMAC.
RECEIVED
Release Notification and Corrective Action

NAB1715654915

OPERATOR
☒ Initial Report ☒ Final Report

Name of Company Devon Energy Production Company <i>6137</i>	Contact Matt Nettles, Production Foreman
Address 6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No. 575-513-5767
Facility Name Cotton Draw Unit 84	Facility Type Salt Water Disposal

Surface Owner State	Mineral Owner State	API No 30-015-29728
----------------------------	----------------------------	----------------------------

LOCATION OF RELEASE

Unit Letter I	Section 2	Township 25S	Range 31E	Feet from the 2615	North/South Line FSL	Feet from the 1160	East/West Line FEL	County Eddy
------------------	--------------	-----------------	--------------	-----------------------	-------------------------	-----------------------	-----------------------	----------------

Latitude: 32.1592751

Longitude: -103.7438736

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 32BBLS	Volume Recovered 32BBLS
Source of Release Filter Pot	Date and Hour of Occurrence 5-1-2017 @ 3:55AM	Date and Hour of Discovery 5/1/2017 @ 3:55AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM-Shelly Tucker OCD-Olivia Yu	
By Whom? David Simmons, Assistant Production Foreman	Date and Hour BLM-5/1/2017 @ 4:20AM OCD-5/1/2017 @ 4:15AM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		

Describe Cause of Problem and Remedial Action Taken.*
 A filter pot ruptured an O-ring causing a release of 32 BBLS PW inside of the containment. The filter pot was isolated to prevent any further release from occurring. Repairs will be made to the equipment.

Describe Area Affected and Cleanup Action Taken.*
 Approximately 32bbls produced water was released inside the lined containment. All 32BBLS of released produced water remained in the containment and was recovered back to the tanks through a sump pump at the facility. The containment and liner were visually inspected and placed back into service.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Dana DeLaRosa	OIL CONSERVATION DIVISION	
Printed Name: Dana DeLaRosa	Signed By <i>[Signature]</i> Approved by Environmental Specialist:	
Title: Field Admin Support	Approval Date: 6/5/17	Expiration Date: N/A
E-mail Address: Dana.Delarosa@dm.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/>
Date: Phone: 575.74.5594		

* Attach Additional Sheets If Necessary

 New forms can be found in the
 New Mexico State Website in forms:
<http://www.emnrd.state.nm.us/OCD/forms.html>

ARP-4235