

WELL SERVICE REPORT

OWNER: POWELL ENERGY LEASE LOWE B WELL: 1 DATE: 10-18-84

FIELD: _____ COUNTY: _____ STATE: _____ T.D.: _____

FLUID LEVEL: _____ PERF. OR O.H.: _____ CASING: _____

REASON FOR WORK: PUMP CHANGE

PULLED		DESCRIPTION OF ITEM	RUN	
FEET	JOINTS		FEET	JOINTS
		PULLED RODS AND PUMP		
		FOUND PUMP TO HAVE A		
		SPLIT BARREL.		
		108 - $\frac{3}{4}$ IN. RODS		
		1 - 8 FT. $\times \frac{3}{4}$ ROD		
		1 - 6 FT. $\times \frac{3}{4}$ "		
		1 - 2 FT. $\times \frac{3}{4}$ "		
		1 - 10 FT. PUMP.		
		PUMP NO. 934 10 FT METAL		
		TRAV. BARREL, 2 $\times$ 1 $\frac{1}{2}$ $\times$ 10		
		DOUBLE VALVE, BOTTOM HUNG DOWN		
		6 $\frac{1}{2}$ IN. STOVE $\frac{5}{8}$ IN. PIN		

REMARKS AND DETAILS OF WORK: _____

SIGNED: P. Lynn Brown

CHECK IF ADDITIONAL REMARKS ON BACK