Submit One Copy To Appropriate CONSERVATION of New Mexico	Form C-103
Pietrict I Energy Minerals and Natural Resources	Revised November 3, 2011 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 JUL 2 7 2017 District II 811 S. First St. Artesia NM 88210 OIL CONSERVATION DIVISION	30-015-23097
811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Rd Aztec, NM 87410 RECEIVED 1220 South St. Francis Dr.	5. Indicate Type of Lease
Conto Fo NM 9/505	STATE FEE
District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Bryan ME
PROPOSALS.)	8. Well Number
1. Type of Well: Oil Well Gas Well Other P&A	1
2. Name of Operator EOG Y Resources, Inc.	9. OGRID Number 025575
3. Address of Operator	10. Pool name or Wildcat
105 South Fourth Street, Artesia, NM 88210	Atoka-Yeso
4. Well Location	
	2310 feet from the West line
Section 33 Township 18S Range 26E	NMPM Eddy County
11. Elevation (Show whether DR, RKB, RT, GR, etc., 3381' GR	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO: SUB	SEQUENT REPORT OF:
PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WOR	-
TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRI	
PULL OR ALTER CASING MULTIPLE COMPL CASING/CEMEN	ГЈОВ 📙
OTHER:	eady for OCD inspection after P&A
 ✓ All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. ✓ Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned. 	
A steel marker at least 4" in diameter and at least 4' above ground level has been set in concrete. It shows the	
ODED (MOD NAME) I FACE NAME WELL MUMBER ADIMUMBER OUADTER/OUADTER LOCATION OF	
<u>OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR</u> UNIT LETTER, SECTION, TOWNSHIP, AND RANGEAll INFORMATION HAS BEEN WELDED OR	
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.	
☐ The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and	
other production equipment.	been eleased of an junk, trash, now mes and
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.	
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed	
from lease and well location. DHM is located on same pad with the Ribbon BDR #1 tank battery (the Bryan battery has been	
removed from the CTB, Unit C, Section 33, T18S-R26E)	
All metal bolts and other materials have been removed. Portable bases have been removed.	ved. (Poured onsite concrete bases do not have
to be removed.)	
 ✓ All other environmental concerns have been addressed as per OCD rules. ✓ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. 	All fluids have been removed from non-
retrieved flow lines and pipelines. No, active pipeline(s) within EOG Y Resources gas system.	
If this is a one-well lease or last remaining well on lease: all electrical service poles and	
location, except for utility's distribution infrastructure. CVE has been notified to retire ele When all work has been completed, return this form to the appropriate District office to sch	
SIGNATURE TITLE: Environmental Su	pervisor DATE <u>7/27/2017</u>
	ogresources.com PHONE: 575-748-4217
For State Use Only DENIED	
APPROVED BY: TITLE	DATE 7/28/2017
Conditions of Approval (if any):	