State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez Governor

Ken McQueen Cabinet Secretary Matthias Sayer

Deputy Cabinet Secretary

David Catanach Division Director



Response Required - Deadline Enclosed

Field Inspection Program "Preserving the Integrity of Our Environment"

01-Aug-17

LINN OPERATING, INC.

600 Travis Street Suite 1400 Houston TX 77002-7002

LETTER OF VIOLATION - Inspection

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

		INSPECTI	ON DETAIL	SECTION				
SKELLY UNIT No.018 Inspection Date Type Inspection		Inspector	Violation?	D-15-17S-31E *Significant Non-Compliance?	30-015-05154-00- Corrective Action Due By:	00 Inspection No.		
08/01/2017	Routine/Perioc Violations General Housekee		Yes	No	11/4/2017	iTM1721347008		
Comments		OK. All Equipment and Location LOCATION 19.15.35.7B	in Good Shape	. CONTAMINATED	D MATERIAL ON			
SKELLY U Inspection				L-15-17S-31E *Significant	30-015-29206-00- Corrective			
Date	Type Inspection	Inspector	Violation?	Non-Compliance?	Action Due By:	Inspection No.		
08/01/2017	Routine/Period Violations		Yes	No	11/4/2017	iTM1721342743		
	General Housekee	ping (Rule 114)						
			uipment and Location in Good Shape. PJ STAINING AROUND WELLHEAD INATED MATERIAL ON LOCATION 19.15.35.7B					

SKELLY UNIT		No.191		J-15-17S-31E	30-015-29312-00-00			
Inspection Date	Type Inspection	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.		
08/01/2017	Routine/Peric	dic Tony Morales	Yes	No	11/4/2017	iTM1721336948		
	Violations							
General Housekeeping (Rule 114)								
Comments on Inspection:		OK. All Equipment and Location in Good Shape. 19.15.35.7B		PJ STAINING AROUND WELLHEAD.				

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. *Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.