

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

NM OIL CONSERVATION
ARTESIA DISTRICT
State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised April 3, 2017
Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.
RECEIVED

OCT 20 2017

Release Notification and Corrective Action

NAB1729753198

OGRI#6370 OPERATOR

☒ Initial Report ☐ Final Report

Name of Company	Devon Energy Production Company	Contact	Matt Nettles, Production Foreman
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-513-5767
Facility Name	Todd 22 I Fed 9	Facility Type	Oil
Surface Owner	Federal	Mineral Owner	Federal
		API No.	30-015-32730

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
I	22	23S	31E	1980'	FSL	660'	FEL	Eddy

Latitude 32.2880936 Longitude -103.7592621 NAD83

NATURE OF RELEASE

Type of Release Oil & Produced Water	Volume of Release 4bbls <u>2 bbl Oil / 2 bbl PW</u>	Volume Recovered 3bbls <u>2 bbl Oil / 1 bbl PW</u>
Source of Release Flow line	Date and Hour of Occurrence October 9, 2017 @ 10:00 AM	Date and Hour of Discovery October 9, 2017 @ 10:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Shelly Tucker, BLM Mike Bratcher, NMOCD	
By Whom? Chris West, Asst. Production Foreman	Date and Hour BLM-October 9, 2017 @ 2:30 PM NMOCD- October 9, 2017 @ 2:40 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* The flow line ruptured. The power to the unit was immediately shut off and the well and flowline were was shut in to stop the release.		
Describe Area Affected and Cleanup Action Taken.* Approximately 2bbls oil and 2bbls produced water were released into the pasture in an area that is approximately 7'x61' near the entrance to the location. Approximately 2bbls oil and 1bbl of produced water was recovered. An environmental contractor will be contacted to assist with the delineation and remediation of the affected area.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: Sheila Fisher		OIL CONSERVATION DIVISION Approved by Environmental Specialist: <u>for record</u>
Printed Name: Sheila Fisher		
Title: Field Admin Support	Approval Date: <u>10/24/17</u>	Expiration Date: <u>NIA</u>
E-mail Address: Sheila.Fisher@dvn.com	Conditions of Approval:	
Date: 10/9/17 Phone: 575.748.1829	Attached <input type="checkbox"/> <u>ARP-4453</u>	

* Attach Additional Sheets If Necessary

10/24/17 AB