## State of New Mexico Energy, Minerals and Natural Resources Department

Susana Martinez

Governor

Ken McQueen


Cabinet Secretary

**Matthias Sayer** 

**Deputy Cabinet Secretary** 

David Catanach

Division Director





Field Inspection Program
"Preserving the Integrity of Our Environment"

10-Jan-18

## DEVON ENERGY PRODUCTION COMPANY, LP

PO Box 250

Artesia NM 88210

**LETTER OF VIOLATION - Inspection** 

Dear Operator:

The following inspection(s) indicate that the well, equipment, location or operational status of the well(s) failed to meet standards of the New Mexico Oil Conservation Division as described in the detail section below. To comply with standards imposed by Rules and Regulations of the Division, corrective action must be taken immediately and the situation brought into compliance. The detail section indicates preliminary findings and/or probable nature of the violation. This determination is based on an inspection of your well or facility by an inspector employed by the Oil Conservation Division on the date(s) indicated.

Please notify the proper district office of the Division, in writing, of the date corrective actions are scheduled to be made so that arrangements can be made to reinspect the well and/or facility.

			INSPECTIO	N DETAIL	SECTION		
TODD 27 M FEDERAL No.013 Inspection Date Type Inspection			Inspector	Violation?	M-27-23S-31E *Significant Non-Compliance?	30-015-27711-00-0 Corrective Action Due By:	00 Inspection No.
01/10/2018	Routine/Periodic Violations Surface Leaks/Spills		Tony Morales	Yes	No	4/15/2018	iTM1801044972
Comments	on Inspection:	FLOWLINE CH	ent and Location in ECK VALVE ME 0.8 TANK BATTE	TER STAIN		EAST OF PJ ON LEASE ROAD APPR	OX 30'
TODD 27 L A FEDERAL No.012					L-27-23S-31E	30-015-27884-00-00	
Inspection Date	Type Inspection	l	Inspector	Violation?	*Significant Non-Compliance?	Corrective Action Due By:	Inspection No.
01/10/2018	Routine/Perio Violations General Houseke		Tony Morales	Yes	No	4/15/2018	iTM1801044784
Comments	on Inspection:	OK. All Equipm 19.15.10.8	ent and Location in	Good Shape	, PJ, STAINING	G AROUND WELL H	EAD

**ALDABRA 27 FEDERAL** 

No.001H

M-27-23S-31E

30-015-38625-00-00

Inspection Date

01/10/2018

**Type Inspection** 

Inspector

Violation?

\*Significant Non-Compliance?

Corrective Action Due By:

Inspection No.

Routine/Periodic

**Tony Morales** 

Yes

No

4/15/2018

iTM1801045102

Violations

General Housekeeping (Rule 114)

**Comments on Inspection:** 

OK. All Equipment and Location in Good Shape.

PJO. STAINING AROUND WELL

HEAD 19.15.10.8

In the event that a satisfactory response is not received to this letter of direction by the "Corrective Action Due By:" date shown above, further enforcement will occur. Such enforcement may include this office applying to the Division for an order summoning you to a hearing before a Divison Examiner in Santa Fe to show cause why you should not be ordered to permanently plug and abandon this well.

Sincerely,

Artesia OCD District Office

Note: Information in Detail Section comes directly from field inspector data entries - not all blanks will contain data. \*Significant Non-Compliance events are reported directly to the EPA, Region VI, Dallas, Texas.