

NM OIL CONSERVATION

ARTESIA DISTRICT

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

JAN 22 2018

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
RECEIVED accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1802429248

OPERATOR

☒ Initial Report ☒ Final Report

Name of Company: XTO Energy	Contact: Kyle Littrell
Address: 522 W. Mermod, Suite 704 Carlsbad, N.M. 88220	Telephone No: 432-221-7331
Facility Name: Big Eddy Unit DI5 Tank Battery (API for BEU DI5 #004H)	Facility Type: Exploration and Production



Surface Owner: Federal	Mineral Owner: Federal	API No: 30-015-40397
------------------------	------------------------	----------------------

LOCATION OF RELEASE

Unit Letter G	Section 27	Township 20S	Range 31E	Feet from the 2530	North/South Line North	Feet from the 1700	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	----------------

Latitude 32.544507° Longitude -103.854020° NAD83

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release 45 bbls	Volume Recovered 45 bbls
Source of Release Oil Tanks	Date and Hour of Occurrence 1/7/2018 time unknown	Date and Hour of Discovery 1/8/2018 12 am
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher/Crystal Weaver (NMOCD), Shelly Tucker/Jim Amos (BLM)	
By Whom? Amy Ruth	Date and Hour: 1/8/2018 7:17 am by email	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	
If a Watercourse was Impacted, Describe Fully.* N/A		
Describe Cause of Problem and Remedial Action Taken.* Oil tanks overflowed into lined containment due to hauling company falling behind schedule.		
Describe Area Affected and Cleanup Action Taken.* The release affected the impermeable lined containment surrounding the oil and produced water tanks at the south end of the facility. No fill material was located inside containment. A XTO EHS Coordinator who is competent in the operation, maintenance, and inspection of all on-site equipment and facilities visually inspected the containment and verified that there was no visual evidence of a liner breach. All free-standing liquids were recovered from the containment and the containment and equipment were power washed.		
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.		
Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Kyle Littrell	Approved by Environmental Specialist: 	
Title: Environmental Coordinator	Approval Date: 1/25/18	Expiration Date: N/A
E-mail Address: Kyle.Littrell@xtoenergy.com	Conditions of Approval: FINAL	Attached <input type="checkbox"/> 
Date: 1/22/2018 Phone: 432-221-7331		

* Attach Additional Sheets If Necessary

1/25/18 ARB