

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

OCD received
on 2/9/18
District II

Form C-141
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

NAB1810639166

OPERATOR		X Initial Report	<input checked="" type="checkbox"/> Final Report
Name of Company	Vanguard Operating, LLC 258350	Contact	Jason Fisher
Address	5847 San Felipe, STE 3000 Houston, TX 77057	Telephone No.	505-918-0523
Facility Name	AID 24 State #9 Battery	Facility Type	Tank Battery
Surface Owner	Mineral Owner State	API No. 3001538188	

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	24	17S	28E	330	South	1650	West	Eddy

Latitude 32.814822 Longitude -104.1330566 NAD83

NATURE OF RELEASE **X2=900 MCF**

Type of Release Gas/Emissions	Volume of Release 450 MCFD	Volume Recovered 0
Source of Release Flare	Date and Hour of Occurrence 2-3-2018	Date and Hour of Discovery N/A
Was Immediate Notice Given? X Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Amalia Bustamante by email	
By Whom? Chuck Johnston	Date and Hour 7:30 pm 2-3-2018	
Was a Watercourse Reached? <input type="checkbox"/> Yes X No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*

N/A

Describe Cause of Problem and Remedial Action Taken.*


Purchaser found leak on their pipeline and requested a volume reduction while making repairs. Gas was sent to flare for two days.

Describe Area Affected and Cleanup Action Taken.*

No impact.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

OIL CONSERVATION DIVISION

Signature: 	Approved by Environmental Specialist: Accepted for review	
Printed Name: Chuck Johnston	Approval Date: 4/12/18	Expiration Date: N/A
Title: EHS Specialist	Conditions of Approval: Final	
E-mail Address: cjohnston@vnrenergy.com	Attached <input type="checkbox"/> 2RP-41697	
Date: 2-9-2018	Phone: 432-202-4771	

* Attach Additional Sheets If Necessary

4/12/18 AB