

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NMLC065478A

6. If Indian, Allottee or Tribe Name

7. If Unit or CA/Agreement, Name and/or No.

SUBMIT IN TRIPLICATE - Other instructions on page 2

8. Well Name and No.
FALCON 3 A FEDERAL 40

9. API Well No.
30-015-43754-00-X1

10. Field and Pool or Exploratory Area
RED LAKE

11. County or Parish, State
EDDY COUNTY, NM

1. Type of Well
☒ Oil Well ☐ Gas Well ☐ Other

2. Name of Operator
LIME ROCK RESOURCES II A LP
Contact: MIKE PIPPIN
E-Mail: mike@pippinllc.com

3a. Address
1111 BAGBY STREET SUITE 4600
HOUSTON, TX 77002

3b. Phone No. (include area code)
Ph: 505-327-4573

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Sec 3 T18S R27E Lot 1 1175FNL 250FEL

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input checked="" type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input checked="" type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input type="checkbox"/> Temporarily Abandon	Well Spud
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomple horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

THIS IS THE SPUD & CASING REPORT FOR A NEW OIL WELL:

Spudded well on 2/21/18. Drilled 12-1/4" hole to 360'. Set 8-5/8" 24# J-55 csg @ 350'. Cmted w/350 sx (469 cf) cl "C" cmt w/2% Cacl2, & 0.125#/sx cello flakes. Circ. 62 sx cmt to surface. On 2/22/18, pressure tested 8-5/8" csg to 1500 psi for 30 min-OK. Drilled 7-7/8" hole to TD4882' on 2/27/18. On 2/28/18, set 5-1/2" 17# J-55 production csg @ 4860'. Cmted lead w/300 sx (588 cf) 35/65 poz cl "C" w/6% gel/PF20, 5% salt/PF44, 0.2% fluid loss/PF606, 0.125#/sx cello flake/PF29, 0.4#/sx antifoamer/PF45, 0.1% retarder/PF13 & 3#/sx kolseal/PF42. Tailed w/600 sx (798 cf) cl "C" cmt w/0.2% fluid loss/PF606, 0.2% dispersant/PF65, & 0.125#/sx cellophane/PF29. Circ 14 sx cmt to surface. Released drilling rig on 3/1/18. Plan to pressure test 5-1/2" csg during completion operations.

BC 4-19-18
Accepted for record - NMOCD

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #406384 verified by the BLM Well Information System
For LIME ROCK RESOURCES II A LP, sent to the Carlsbad
Committed to AFMSS for processing by PRISCILLA PEREZ on 03/06/2018 (18PP1218SE)**

Name (Printed/Typed) MIKE PIPPIN

Title PETROLEUM ENGINEER

Signature (Electronic Submission)

Date 03/02/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By

ACCEPTED

(BLM Approver Not Specified)

Title

Date 04/05/2018

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office Carlsbad

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Additional data for EC transaction #406384 that would not fit on the form

32. Additional remarks, continued

Revisions to Operator-Submitted EC Data for Sundry Notice #406384

	Operator Submitted	BLM Revised (AFMSS)
Sundry Type:	SPUD SR	SPUD SR
Lease:	NMLC065478B	NMLC065478A
Agreement:		
Operator:	LIME ROCK RESOURCES II-A, L.P. C/O MIKE PIPPIN 3104 N. SULLIVAN FARMINGTON, NM 87401 Ph: 505-327-4573	LIME ROCK RESOURCES II A LP 1111 BAGBY STREET SUITE 4600 HOUSTON, TX 77002 Ph: 713.292.9510
Admin Contact:	MIKE PIPPIN PETROLEUM ENGINEER E-Mail: MIKE@PIPPINLLC.COM Ph: 505-327-4573	MIKE PIPPIN PETROLEUM ENGINEER E-Mail: mike@pippinllc.com Ph: 505-327-4573
Tech Contact:	MIKE PIPPIN PETROLEUM ENGINEER E-Mail: MIKE@PIPPINLLC.COM Ph: 505-327-4573	MIKE PIPPIN PETROLEUM ENGINEER E-Mail: mike@pippinllc.com Ph: 505-327-4573
Location:		
State:	NM	NM
County:	EDDY	EDDY
Field/Pool:	RED LAKE, GL-YESO NE 96836	RED LAKE
Well/Facility:	FALCON 3 A FEDERAL 40 Sec 3 T18S R27E NENE 1175FNL 250FEL	FALCON 3 A FEDERAL 40 Sec 3 T18S R27E Lot 1 1175FNL 250FEL