

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

MAY 30 2018

Form C-141  
Revised April 3, 2017

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.  
**DISTRICT II-ARTESIA O.C.D.**

**Release Notification and Corrective Action**

*NAB1815742127*

**OPERATOR**

Initial Report  Final Report

Name of Company <i>Devon Energy Production Company</i> <i>6137</i>	Contact <i>Steve McGlassen, Production Foreman</i>
Address <i>6488 Seven Rivers Hwy Artesia, NM 88210</i>	Telephone No. <i>575-748-3371</i>
Facility Name <i>Agate 21 PWU 11H</i>	Facility Type <i>Oil</i>

Surface Owner State	Mineral Owner State	API No. <i>30-015-44200</i>
---------------------	---------------------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<i>I</i>	<i>20</i>	<i>19S</i>	<i>29E</i>	<i>1420'</i>	<i>FSL</i>	<i>550'</i>	<i>FEL</i>	<i>Eddy</i>

Latitude *\_32.6429765\_* Longitude *\_104.0901813\_* NAD83

**NATURE OF RELEASE**

Type of Release <i>Natural Gas</i>	Volume of Release <i>289.7 MCF</i>	Volume Recovered <i>0 MCF</i>
Source of Release <i>Relief Valve</i>	Date and Hour of Occurrence <i>May 15, 2018 @ 2:00 PM</i>	Date and Hour of Discovery <i>May 15, 2018 @ 2:00 PM</i>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. <i>N/A</i>	

If a Watercourse was Impacted, Describe Fully.\*  
*N/A*

Describe Cause of Problem and Remedial Action Taken.\*  
*Relief valve on buy back gas line popped off causing gas release. The well was shut in to stop the release and repairs have been made.*

Describe Area Affected and Cleanup Action Taken.\*  
*Approximately 289.7 MCF was released.*

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Dana DeLaRosa</i>		<b>OIL CONSERVATION DIVISION</b>	
Printed Name: <i>Dana DeLaRosa</i>		Approved by Environmental Specialist <i>[Signature]</i>	
Title: <i>Field Admin Support</i>		Approval Date: <i>6/15/18</i>	Expiration Date: <i>N/A</i>
E-mail Address: <i>Dana.Delarosa@dvn.com</i>		Conditions of Approval: <i>FINAL</i>	
Date: <i>5/30/2018</i> Phone: <i>575.746.5594</i>		Attached <input checked="" type="checkbox"/> <i>289.4774</i>	

\* Attach Additional Sheets If Necessary