

UNITED STATES
DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

FORM APPROVED
OMB NO. 1004-0137
Expires: January 31, 2018

SUNDRY NOTICES AND REPORTS ON WELLS
Do not use this form for proposals to drill or to re-enter an abandoned well. Use form 3160-3 (APD) for such proposals.

5. Lease Serial No.
NMNM04557

6. If Indian, Allottee or Tribe Name

SUBMIT IN TRIPLICATE - Other instructions on page 2

7. If Unit or CA/Agreement, Name and/or No.

8. Well Name and No.
BIG EDDY 33

9. API Well No.
30-015-20369-00-C1

10. Field and Pool or Exploratory Area
S HACKBERRY

11. County or Parish, State
EDDY COUNTY, NM

1. Type of Well
 Oil Well Gas Well Other

2. Name of Operator
BOPCO LP

Contact: **TRACIE J CHERRY**
E-Mail: **tracie_cherry@xtoenergy.com**

3a. Address
**6401 HOLIDAY HILL RD BLDG 5 SUITE 200
MIDLAND, TX 79707**

3b. Phone No. (include area code)
Ph: **432-221-7379**

4. Location of Well (Footage, Sec., T., R., M., or Survey Description)
Sec 4 T20S R31E SESE 660FSL 660FEL

12. CHECK THE APPROPRIATE BOX(ES) TO INDICATE NATURE OF NOTICE, REPORT, OR OTHER DATA

TYPE OF SUBMISSION	TYPE OF ACTION			
<input checked="" type="checkbox"/> Notice of Intent	<input type="checkbox"/> Acidize	<input type="checkbox"/> Deepen	<input type="checkbox"/> Production (Start/Resume)	<input type="checkbox"/> Water Shut-Off
<input type="checkbox"/> Subsequent Report	<input type="checkbox"/> Alter Casing	<input type="checkbox"/> Hydraulic Fracturing	<input type="checkbox"/> Reclamation	<input type="checkbox"/> Well Integrity
<input type="checkbox"/> Final Abandonment Notice	<input type="checkbox"/> Casing Repair	<input type="checkbox"/> New Construction	<input type="checkbox"/> Recomplete	<input type="checkbox"/> Other
	<input type="checkbox"/> Change Plans	<input type="checkbox"/> Plug and Abandon	<input checked="" type="checkbox"/> Temporarily Abandon	
	<input type="checkbox"/> Convert to Injection	<input type="checkbox"/> Plug Back	<input type="checkbox"/> Water Disposal	

13. Describe Proposed or Completed Operation: Clearly state all pertinent details, including estimated starting date of any proposed work and approximate duration thereof. If the proposal is to deepen directionally or recomplate horizontally, give subsurface locations and measured and true vertical depths of all pertinent markers and zones. Attach the Bond under which the work will be performed or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recomplate in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has determined that the site is ready for final inspection.

BOPCO, LP respectfully submits this sundry notice to temporarily abandon the referenced well. Well is not being P&A'd at this time to allow for possible recomplate uphole at a later date.

*GC 6-14-18
Accepted for record - NMOCD*

1. MIRU workover unit. Blow well down if needed. POOH with pump and rods. ND WH and NU 5K BOP and test. Release TAC and POOH with same on 227/8" tubing string.

RECEIVED

2. RIH with gauge ring/junk basket and CCL to PBTD +/- 11,657' and tag. Pull short strip log from 11,657' to 8,100'. POOH with tools.

JUN 13 2018

3. RIH with CCL and 10K CIBP for 5-1/2", 20# casing. Set CIBP at 11,420'. Tag to verify plug is set.

DISTRICT II-ARTESIA O.C.D.

14. I hereby certify that the foregoing is true and correct.

**Electronic Submission #421623 verified by the BLM Well Information System
For BOPCO LP, sent to the Carlsbad
Committed to AFMSS for processing by PRISCILLA PEREZ on 05/30/2018 (18PP1837SE)**

Name (Printed/Typed) TRACIE J CHERRY	Title REGULATORY ANALYST
Signature (Electronic Submission)	Date 05/29/2018

THIS SPACE FOR FEDERAL OR STATE OFFICE USE

Approved By /s/ Jonathon Shepard Title PE Date 6/6/18

Conditions of approval, if any, are attached. Approval of this notice does not warrant or certify that the applicant holds legal or equitable title to those rights in the subject lease which would entitle the applicant to conduct operations thereon.

Office CFO

Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

**** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ** BLM REVISED ****

Additional data for EC transaction #421623 that would not fit on the form

32. Additional remarks, continued

4. RIH with bailer, tag CIBP at 11,420' and dump bail 35' Class 'H' cement (~3.5 sacks + 2 sacks excess) on top of CIBP. Est. PBTD at 11,385'. Tag.
5. Load well with 2% KCl and pressure test casing and CIBP to 500 psi for 30 mins.
6. Circulate hole with 9.5# Salt Gel from 11,300' to 9,500'.
7. PUH to +/- 10,400', spot 25 sxs Class 'H' cmt from 10,450' to 10,200'. WOC & Tag. (T/ Wolfcamp)
8. PUH to ~10,000', spot 25 sxs Class H Cmt from 10,000' to 9,750'. WOC & Tag. (Bone Spring 2 Carb, Perf Plug)
9. Perform MIT ? load casing with packer fluid and biocide and pressure test to 500 psi for 30 mins.


BLM will be notified prior to setting of plugs.



CURRENT

Schematic - Vertical
Well Name: BIG EDDY 033

API/UVI 3001520369	Accounting ID 996651	Permit Number	State/Province New Mexico	County Eddy
Surface Location T20S-R31E-S04	Spud Date 2/3/1971	Original KB Elevation (ft) 3,495.00	Gr Elev (ft) 3,483.00	KB-Ground Distance (ft) 12.00
Field Name Hackberry Strawn, South 29460	North/South Distance (ft) 660.0	North/South Reference FSL	East/West Distance (ft) 660.0	East/West Reference FEL
Well Classification Oil	Well Type	Well Status Shut-In	Latitude (°) 32° 35' 47.976" N	Longitude (°) 103° 52' 2.172" W
			Method Of Production Beam	






PROPOSED

Schematic - Vertical
Well Name: BIG EDDY 033

API/Well 3001520369	Accounting ID 996651	Permit Number	State/Province New Mexico	County Eddy
Surface Location T20S-R31E-S04	Spud Date 2/3/1971	Original KB Elevation (ft) 3,495.00	Gr Elev (ft) 3,483.00	KB-Ground Distance (ft) 12.00
Field Name Hackberry Strawn, South 29460	North/South Distance (ft) 660.0	North/South Reference FSL	East/West Distance (ft) 660.0	East/West Reference FEL
Well Classification Oil	Well Type	Well Status Shut-in	Latitude (°) 32° 35' 47.976" N	Longitude (°) 103° 52' 2.172" W
			Method Of Production Beam	



BUREAU OF LAND MANAGEMENT
Carlsbad Field Office
620 East Greene Street
Carlsbad, New Mexico 88220
575-234-5972

Temporary Abandonment of Wells on Federal Lands
Conditions of Approval

A temporarily abandoned well is defined as a completion that is not capable of production in paying quantities but which may have value as a service well. Pursuant to 43 CFR 3162.3-4 (c), no well may be temporarily abandoned for more than 30 days without the prior approval of the authorized officer.

Temporary Abandonment (TA) status approval requires a successful mechanical or casing integrity test as follows:

1. A Notice of Intent (NOI) Sundry Notice (Form 3160-5) requesting approval to run a mechanical integrity test (MIT) or casing integrity test (CIT).
2. A description of the temporary abandonment procedure.
 - a. A bridge plug or packer must be installed as close to 50 feet above any open perforations or open hole as possible. If a cement plug is used, the top of the cement must be verified by tagging. CIBP must be capped with minimum 25 sacks cement, placed with tubing, or 35 feet of cement if placed with bailer.
 - b. The wellbore must be filled with corrosion inhibited fluid and pressure tested to 500 psi. The casing shall be capable of holding this pressure for at least 30 minutes. Any leak-off will be evaluated.
 - c. All downhole production/injection equipment (tubing, rods, etc.) shall be removed from the casing if they are not isolated by a packer.
 - d. A bradenhead test must be conducted. If the test indicates a problem exists, a remedial plan and time frame for remediation shall be submitted within ninety (90) days of the test.
 - e. Contact the appropriate BLM office at least 24 hours prior to the scheduled Casing Integrity Test. For wells in Eddy County, 575-361-2822; Lea County 575-393-3612.
3. **Provide justification why the well should be temporarily abandoned rather than permanently plugged and abandoned and an estimated date that the well will be returned to beneficial use or plugged and abandoned. 43 CFR 3162.3-4 (a) The operator shall promptly plug and abandon...wells in which oil or gas is not encountered in paying quantities...**

Wells that successfully pass the casing integrity test **may** be approved for Temporary Abandonment (TA) status provided that the operator:

1. **Submits a subsequent Sundry Notice** (Form 3160-5) requesting TA approval **with well bore diagram** with all perforations and CIBP's and tops of cement on CIBP's.
2. Describes the temporary abandonment procedure.
3. Attaches a clear copy or the original of the pressure test chart.
4. Give justification to allow well to be place in TA status and plan for future use of well with time frame that well will be place back on line or plans to P&A well will be submitted.

If the well does not pass the casing integrity test, then the operator shall within 30 days submit to BLM for approval one of the following:

1. A procedure to repair the casing so that a TA approval can be granted.
2. A procedure to plug and abandon the well.