## DEC 0 7 2018

	of New Mexico	Form C-103 January 20, 2011
District I		WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II		30-015-01700
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease
District III 1220 South St. Francis Dr.		STATE STATE
1000 Rio Brazos Rd., Aztec, NM 87410 District IV Santa Fe, NM 87505		6. State Oil & Gas Lease No.
1220 S. St. Francis Dr., Santa Fe, NM 87505		
SUNDRY NOTICES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Amoco State A
PROPOSALS.)		8. Well Number 1
1. Type of Well: Oil Well Gas Well Other		O OCRID Number
2. Name of Operator COG Operating LLC		9. OGRID Number 229137
3. Address of Operator		10. Pool name or Wildcat
600 W. Illinois Ave., Midland Texas 79701		Artesia; QN-Grbg-SA
4. Well Location		1
Unit Letter A: 505 feet from the North line and 660 feet from the East line		
Section 34 Township 17S Range 28E NMPM County Eddy		
The state of the s	whether DR, RKB, RT, GR, etc	
<u>3686</u> ' GR		
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data		
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:		
PERFORM REMEDIAL WORK   PLUG AND ABANDO		
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐ COMMENCE DRILLING OPNS.☐ P AND A		
PULL OR ALTER CASING	☐ CASING/CEMEN	IT JOB
OTHER:		
All pits have been remediated in compliance with OCD rules and the terms of the Operator's pit permit and closure plan.  Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.		
Rat hole and cellar have been filled and leveled. Cathodic protection holes have been properly abandoned.  A steel marker at least 4" in diameter and at least 4" above ground level has been set in concrete. It shows the		
OPERATOR NAME, LEASE NAME, WELL NUMBER, API NUMBER, QUARTER/QUARTER LOCATION OR		
UNIT LETTER, SECTION, TOWNSHIP, AND RANGE. All INFORMATION HAS BEEN WELDED OR		
PERMANENTLY STAMPED ON THE MARKER'S SURFACE.		
The location has been leveled as nearly as possible to original ground contour and has been cleared of all junk, trash, flow lines and		
other production equipment.  Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
Anchors, dead men, tie downs and risers have been cut off at least two feet below ground level.		
If this is a one-well lease or last remaining well on lease, the battery and pit location(s) have been remediated in compliance with		
OCD rules and the terms of the Operator's pit permit and closure plan. All flow lines, production equipment and junk have been removed from lease and well location		
from lease and well location. T B Area Not clearly Level.  All metal bolts and other materials have been removed. Portable bases have been removed. (Poured onsite concrete bases do not have		
to be removed ) 0 1 0 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1		
to be removed.) All other environmental concerns have been addressed as per OCD rules.  ☐ Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
Pipelines and flow lines have been abandoned in accordance with 19.15.35.10 NMAC. All fluids have been removed from non-		
retrieved flow lines and pipelines.		
If this is a one-well lease or last remaining well on lease, all electrical service, poles and lines, not to include primary service		
company equipment, has been removed from lease and wel When all work has been completed, return this form to the		hadula an inspection
when an work has been completed, return this form to the	appropriate District office to se	neduce an inspection.
SIGNATURE MALTIA CLAIM		
SIGNATURE ON LAND	TITLE Operations Engineer	ng Tech DATE <u>12/6/18</u>
<b>.</b>	T	PMOVE 422 010 0210
TYPE OR PRINT NAME Onetha Aaron	E-MAIL: oaaron@concho.c	
For State Use Only		G C ,
APPROVED BY:	TITLE	DATE 12/21/18
Conditions of Approval (if any):		JIED